

MJ 1 1 - A

MJ11-A

THE FOLLOWING MODULES/ASSEMBLIES ARE CONTAINED IN THIS DEVICE.
EACH MAY HAVE ASSOCIATED TECH TIPS, DEC-O-LOG AND FCO's DOCUMENTED
IN THE MODULE/ASSEMBLY CATEGORY OF THE MICROFICHE LIBRARY

G114

G235

H217

H744

H745

M8148

M8149

54-11086

54-11553

54-11581

54-11583

70-06501

70-09769

70-10208

70-10214

70-10497

70-10498

70-10532

70-10580

70-10581

70-10694

70-10695

70-10780

70-10791

70-10824

70-10826

70-10974

70-10975

70-11027

70-11222

70-11223

FCR

MJ11
MEMORY TIMING AND CONTROL
FCO Cross Reference

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

■ **M8148-80003 OCT 78**

QUICK SYNOPSIS

Eliminates timing drift of READ TIMING
DELAY LINE DRIVER.

QUICK CHECK

Wire between C84 and D2 (cathode)

NEW REVISION

Rework etch A to CS C.

■ **M8148-80004 JUL 78**

QUICK SYNOPSIS

Eliminates intermittent system software
failures.

QUICK CHECK

Nylon screws hold H873 to M8148

NEW REVISION

Rework etch A to CS A1.

■ **G235-80008 SEP 78**

QUICK SYNOPSIS

Memory is marginal due to high drive current.

QUICK CHECK

75 ohm resistor at + symbol near large etch

NEW REVISION

Rework etch D to CS N

■

MM 1 1

THE FOLLOWING MODULE/ASSEMBLIES ARE CONTAINED IN THIS DEVICE. EACH MAY HAVE ASSOCIATED TECH TIPS,
DEC-O-LOG AND FCO'S DOCUMENTED IN THE MODULE/ASSEMBLY CATEGORY OF THE MICROFICHE LIBRARY.

70-06468
70-07263
70-09562

G102
G103
G109
G110
G225
G226
G231
G615
G616
G645

H213
H214

M109
M229
M1091
M7290

THE TOP SECRET

FIELD SERVICE TECHNICAL MANUAL				Option or Designator M111			
12 BK	<input type="checkbox"/>	16 BK	<input checked="" type="checkbox"/>	18 BK	<input type="checkbox"/>	28 BK	<input type="checkbox"/>

Title QUALADYNE 1540 SENSE AMPS				Tech Tip M111 Number 01	
All	Processor Applicability		Author DON KRESKI	Rev A	
			Approval CHUCK DEWEY	Date 6/27/72	
Cross Reference					

The Qualadyne 1540 sense amps have had bonding problems. The unit is used in most current DEC sense amplifier boards. The Motorola 1540 should be used as its replacement when necessary. Most of the defective units have been replaced during production. These were used in M111-E and M111-F.

Since the Motorola 1540 units are in production, production is only replacing failing units and are not retrofitting all boards in all product lines. Machines in the field that exhibit strange memory problems that can be localized to sense amp problems should be checked for Qualadyne units with the following date codes: 7014, 7016, 7020, 7022, 7024, 7031, and 7032. These units may be defective and should be replaced as a last resort. We are not suggesting a purge of all Qualadyne units of the above mentioned date codes or future Qualadyne units.

Title M207E MEMORY STACK				Tech Tip M111 Number 02	
All	Processor Applicability		Author TOM KARPONSKI	Rev A	
			Approval CHUCK DEWEY	Date 6/27/72	
Cross Reference					

The M111-E memory will be using a new stack, RCA's M207E. This stack can only be used in an M111-E. The M207 stack can be used in an M111-E and M111-F.

Title M111-E & F/G102 MODULES				Tech Tip M111 Number 03	
All	Processor Applicability		Author TOM KARPONSKI	Rev F	
			Approval CHUCK DEWEY	Date 6/1/72	
Cross Reference					

ECO G102-00005 has been written to make the G102 module capable of running in the M111-F memory. This ECO makes this module CS revision D. It has to be at least revision D to run in an M111-F. This revision can also be used in M111-E's. Please see that your spares are modified accordingly.

Title INTERLEAVING THE M111-E MEMORY				Tech Tip M111 Number 04	
All	Processor Applicability		Author JOHN BUYERSKI	Rev g	
			Approval CHUCK DEWEY	Date 6/1/72	
Cross Reference					

Interleaving is simply addressing the memory such that adjacent memory banks are selected on alternate cycles. Thus, it is interleavable in 8K increments or blocks. This is implemented by interchanging BUS A011 and BUS A11L inputs to the memory between the bus inputs and memory device select and control. The memory being addressed, for example, in a DATA mode is free to complete its cycle after the MEMORY ADDRESS dialog and as soon as the setup times for the bus are satisfied, MEMORY can be asserted to

Title INTERLEAVING THE M811-E MEMORY (Continued)		Tech Tip M811 Number 04	
All	Processor Applicability	Author JOHN BUTYNSKI Rev 0	Cross Reference
		Approved CHUCK DE VY Date 6/1/72	

start a memory cycle in the adjacent memory bank while the first memory bank is completing its cycle. A significant increase in memory throughput occurs.

In the M811-E the two address bits have to be physically interchanged on the back-planes. It is also necessary to modify N729 control logic module to speed up the SSYKL reset circuit. (Refer to BCO's M811-E Numbers 17, 19, and 20; N729 number 2; and BCO M1091 number 1).

Remember, when troubleshooting an interleaved memory, that successive addresses reference alternate memory banks.

Title FIELD INSTALLATION OF M811-E ON FDP-11/45		Tech Tip M811 Number 05	
All	Processor Applicability	Author ANDY VEROSTIC Rev 0	Cross Reference
	11/45	Approved ART SIMS Date 6/7/72	

HARDWARE

Existing N729 control must have BCO #N729-00003 installed for operation on 11/45.

DIAGNOSTICS

All present memory tests will run on the 11/45.

Title FIELD INSTALLATION OF M811-F ON FDP-11/45		Tech Tip M811 Number 06	
All	Processor Applicability	Author ANDY VEROSTIC Rev A	Cross Reference
	11/45	Approved ART SIMS Date 6/7/72	

HARDWARE

Existing N7290 control must have BCO's #N7290-00002 and #00003 installed for proper operation on the 11/45.

DIAGNOSTICS

All present memory tests run on the 11/45.

FIELD SERVICE TECHNICAL MANUAL				Option or Designator
12 Bk <input type="checkbox"/> 16 Bk <input checked="" type="checkbox"/> 18 Bk <input type="checkbox"/> 36 Bk <input type="checkbox"/>				M111
Title			Tech Tip M111-TT	
M111-E and F MEMORY ADDRESS SELECTION AND INTERLEAVING			Number 07	
Processor Applicability		Author	Rev	Cross Reference
AM		Chuck Dewey	0	
		Approval	Date	
		Chuck Dewey	9/28/72	

Address Selection

M111-E Memories have had two types of address selection modules. The M109 was the original address selector and may still be found in some installations. The M109 causes insertion of two UNIBUS unit loads. This was corrected when the M1091 was introduced (ECO M1091-00001). Selection of addresses when using M109 is described in the hardware manual (DEC-11-HR13-D).

Both the M111-E and M111-F memories now utilize M1091 address selector modules. Figure 2 shows the circuit schematic of the M1091 address selection logic. Figure 1 shows a layout of that portion of the physical module where the addressing is accomplished by insertion or removal of jumper wires. Table 1 lists the following:

- a. Bank Number - These numbers are indicative of the physical system units of M111-E or F memories.
- b. K Words - This indicates the word quantity for a specific bank in thousands (K) words.
- c. Addresses - The inclusive (octal) word (two byte) addresses within a specific bank of memory are listed here. They assume a non-interleaved configuration.
- d. Bits 17, 16, 15, 14, 13 and 01 Non-Interleaved - These columns show, by an X, that jumper which should be installed in order to respond to a specific memory bank addressing. The 1, 0, A, B, C and D correspond to the identification shown on the module, figure 1, and figure 2.
- e. Bits 13, and 01 Interleaved - These two bits accomplish the interleaving for M111-F memories and are to be used in place of their counterparts listed for d, above. When used these cause modification of two 4K Banks so that their addressing has the lower (odd) bank with addresses ending with 0 or 4 and upper (even) bank ending with 2 or 6.


Title		M11-E and F MEMORY ADDRESS SELECTION AND INTERLEAVING		Tech Tip		M11-TT	
Author		Chuck Dewey		Number		07	
Processor Applicability		Rev		Date		Cross Reference	
All		9		9/28/72			
Approval		Chuck Dewey					


Interleaving

Interleaving for M11-E memories is described in Tech Tip M11 number 4. It can only be accomplished by system unit wire changes to the back plane. Refer to the ECO's, listed in the Tech Tip, for proper implementation.

M11-F interleaving is accomplished by manipulation of jumper wires on the M1091 module. These changes are shown in Table 1. It is a normal procedure for the production line to interleave all 8K segments of M11-F memory on the initial system prior to shipment.

Interleaving of a M11-E with an M11-F is not recommended primarily due to the confusion it creates when troubleshooting a system of this nature. It also creates customer misunderstanding since the average memory cycle time specification, in this situation, would not be either the M11-E or F but somewhere in between.





Title MM11-E and F MEMORY ADDRESS SELECTION & INTERLEAVING (CONT'D)				Tech Tip MM11-TT Number 87	
Processor Applicability		Author Chuck Dewey		Rev 8	
AR		Approval Chuck Dewey		Date 9/28/72	
Cross Reference					

TABLE 1

Bank	K WORDS	ADDRESSES		NON-INTERLEAVED MM11-F AND ALL MM11-E MEMORIES								INTERLEAVED MM11-F MEMORY *			
		FROM	TO	17	16	15	14	13	01	13	01	13	01	13	01
				10	10	10	10	10	10	10	10	10	10	10	10
1	0-4	00000	017776	X	X	X	X	X	X	X	X	X	X	X	
2	4-8	02000	037776	X	X	X	X	X	X	X	X	X	X	X	
3	8-12	04000	057776	X	X	X	X	X	X	X	X	X	X	X	
4	12-16	06000	077776	X	X	X	X	X	X	X	X	X	X	X	
5	16-20	10000	117776	X	X	X	X	X	X	X	X	X	X	X	
6	20-24	12000	137776	X	X	X	X	X	X	X	X	X	X	X	
7	24-28	14000	157776	X	X	X	X	X	X	X	X	X	X	X	
FROM THIS POINT ON A DEVICE SUCH AS MX11, KS11, OR KT11 IS REQUIRED															
8	28-32	16000	177776	X	X	X	X	X	X	X	X	X	X	X	
9	32-36	20000	217776	X	X	X	X	X	X	X	X	X	X	X	
10	36-40	22000	237776	X	X	X	X	X	X	X	X	X	X	X	
11	40-44	24000	257776	X	X	X	X	X	X	X	X	X	X	X	
12	44-48	26000	277776	X	X	X	X	X	X	X	X	X	X	X	
13	48-52	30000	317776	X	X	X	X	X	X	X	X	X	X	X	
14	52-56	32000	337776	X	X	X	X	X	X	X	X	X	X	X	
15	56-60	34000	357776	X	X	X	X	X	X	X	X	X	X	X	
16	60-64	36000	377776	X	X	X	X	X	X	X	X	X	X	X	
17	64-68	40000	417776	X	X	X	X	X	X	X	X	X	X	X	
18	68-72	42000	437776	X	X	X	X	X	X	X	X	X	X	X	
19	72-76	44000	457776	X	X	X	X	X	X	X	X	X	X	X	
20	76-80	46000	477776	X	X	X	X	X	X	X	X	X	X	X	
21	80-84	50000	517776	X	X	X	X	X	X	X	X	X	X	X	
22	84-88	52000	537776	X	X	X	X	X	X	X	X	X	X	X	
DB11 REQUIRED FROM THIS POINT IF M11 IS IN USE															
23	88-92	54000	557776	X	X	X	X	X	X	X	X	X	X	X	
24	92-96	56000	577776	X	X	X	X	X	X	X	X	X	X	X	
25	96-100	60000	617776	X	X	X	X	X	X	X	X	X	X	X	
26	100-104	62000	637776	X	X	X	X	X	X	X	X	X	X	X	
27	104-108	64000	657776	X	X	X	X	X	X	X	X	X	X	X	
28	108-112	66000	677776	X	X	X	X	X	X	X	X	X	X	X	
29	112-116	70000	717776	X	X	X	X	X	X	X	X	X	X	X	
30	116-120	72000	737776	X	X	X	X	X	X	X	X	X	X	X	
31	120-124	74000	757776	X	X	X	X	X	X	X	X	X	X	X	

BUS ADDRESSING BEYOND THIS POINT RESERVED FOR DEVICES

X DENOTES JUMPER INSERTION ON THE BOARD AT THE IDENTIFIED POINT

* INTERLEAVING CAN ONLY BE ACCOMPLISHED WITH 8K SEGMENTS OF MEMORY. THE XXXXX0 AND XXXXX4 ADDRESSES ARE TO BE ASSIGNED TO ODD BANK MEMORIES

FIELD SERVICE TECHNICAL MANUAL				Option or Designator
12 Bk <input type="checkbox"/>	16 Bk <input type="checkbox"/>	18 Bk <input type="checkbox"/>	36 Bk <input type="checkbox"/>	M11
Title DATA ERRORS CAUSED BY DCLO OR INIT ON M11-K, L, M, S			Tech Tip Number	M11 #8
Processor Applicability		Author A. Verostic/D. Dickhut	Rev #	Cross Reference
Approval Art zins		Date	9/27/72	

A problem exists with the 4K-8K PDP-11 memory (M11-S, M11, M11-L) that appears to be hardware data errors, but disappears if every word in memory is accessed. The problem can appear whenever Initialize or DCLO occurs during a memory cycle. This turns off the X-Y current drivers at the wrong time, leaving some cores in a partially switched state. These half-selected cores contribute large amounts of noise when accessing other words, causing intermittent failures.

DCLO occurring during a memory cycle can be eliminated if the power fail trap is used properly. The power fail trap sequence should turn off any peripheral that might access memory (individually, not by using INIT) and halt the processor before DCLO occurs.

The chances of INIT occurring during a memory cycle will be reduced if software avoids using the RESET instruction, particularly inside tight loops. The condition of half selected cores can be cured by accessing every word in memory to assure all cores are fully switched. Once this is completed, data may be read and written normally.

Title MM11-K, L, M, and S Field Problem Summary		Tech Tip MM 11 Number TT-9	
All 	Processor Applicability	Author D. Dickhut	Rev #
		Approval C. Dewey	Date 11/20/72
Cross Reference			

This Tech Tip is a summary of field problems and their solutions for the MM11-K, L, M, and S memories which are found in ME11L which uses only MM11-L, 11/05 and 11/10 which use MM11-K (4K) 11/05 only and MM11-L (8K), 11/40 which uses only MM11-L (8K), and 11/45 which uses only MM11-S (8K).

1. Random Memory Locations are Altered During Power Fail

The contents may be altered while running Power Fail Diagnostic or by simply turning the machine on and off. ECO G231-5 solves this problem.

2. Memories do not have to be swapped as a system (all 3 modules)

Each system that is shipped has a serial number stamped on side 2 of each module. This number is the same on all 3 modules and is strictly for in-house test purposes only. The memories can be and should be maintained on a module swap basis instead of a system basis (stack not swapped anyway). The system serial number can be used in a case where much swapping has taken place and now the modules are to be put back in their original configuration. By matching the serial number, each system can be reunited and a lot of adjustment time can be saved.

3. What adjustments to make when a module is swapped.

When anyone of the 3 modules that make up the memory system is swapped, the strobe adjustment must be made to ensure system reliability (When the G110 module is swapped, it has the strobe pot but the setting cannot be taken for granted) The procedure to use for strobe adjustment is as follows:

1. If strobe adjustment is too far off, EXAM and DEP may not work. To get strobe in the ballpark, sync on pin CU2 of the G110 model (signal READ H) and Test Point 5 of E05 pin 9 for strobe. Press EXAM rapidly and adjust strobe using pot on G110 for a 250 ns delay from rising edge of READ H to rising edge of strobe. This should allow diagnostics to be read in.
2. Load Worst Case Noise Diagnostic (W.C.N. should be used not a Branch SELP)
3. Load Address 200 and START or Load Address 202 to select the desired bank.
4. Sync on pin CU2 of G110 (signal READ H) while scooping Test Point 5 or E05 pin 9 for strobe and margin strobe by turning pot CW until the diagnostic fails and then CCW until it fails. A complete pass of the diagnostic should be made (within reasonable limits for large core systems) at each high and low end point to ensure that is the true end point. Notice the time from the leading edge of READ H to strobe in each case. The total strobe window should be 40 ns or greater and set strobe in the middle of the high and low points. If the window isn't at least 40 ns, then the entire system should be changed because margin problems can only be dealt with back at Module Repair Depot.

This procedure is graphically illustrated and explained in the ME11L, MM11-S, 11/05, and 11/40 manuals.

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM 11

Title	1011-K, L, M, and S Field Problem Summary (Continued)	Tech Tip Number	MM 11 TT-9
AM	Processor Applicability	Author D. Dickhut	Rev 9
		Approval C. Drwey	Date 11/20/72
		Cross Reference	

4. DEC memory stack threshold problem

Some DEC or RCA memory stacks (DEC stack identified by label on side 2; some may have RCA stickers) have a threshold problem and will not exhibit the normal threshold margins. In order to use these previously rejected stacks in production, the sense circuitry on the G110 was modified. In the field, if a memory stack is swapped and it is a DEC stack, the G110 module should be checked to see if ECO 88 is installed. If it isn't and this is a non-Field effect ECO, a G110 module with that ECO should be obtained from the Maynard Module Repair Depot. The new DEC stack may or may not have this problem and probably will operate properly even if it does. However, with large systems or several NPR (DMA) devices, intermittent failures may occur over a long period of time.

Title ECO DOCUMENTATION FOR THE 9011K, 9011L and 9011S MEMORIES				Tech Tip Number		9011 TT-10	
All		Processor Applicability		Author G. Cable		Rev #	
				Approval C. Dewey		Date 12/12/72	
Cross Reference							

The following Tech Tip will attempt to clarify the confusion regarding the ECO status for the 9011S, 9011K and 9011L memories.

G110 Modules

In the near future there will be two separate types of G110 Modules in the field. The first type of G110 Module is an Etch Revision C Module which already exists in the field. The second type of module will be an Etch Revision E.

It will not be possible to ECO the Etch Revision C Module so that it will be electrically equal to the Etch Revision E Module. For this reason it has become necessary to create two separate sets of engineering drawings to cover the two different modules.

The engineering drawings for the Etch Revision C Module will have a circuit schematic revision of E with one numeric digit following. Each ECO released will increment the numeric digit by one (i.e. E1, E2, E3, and etc.).


The engineering drawings for the Etch Revision E Module will have a circuit schematic revision of an alpha character starting at F and continuing sequentially (i.e. F, M, J, A, and etc.).

Below is a chart that shows the revisions for the two G110 Modules.

G110 Etch Revision C	
ECO No.	CS Revision
G110-0001	A
G110-0002	B
G110-0003	N/A
G110-0003A	N/A
G110-0004	D
G110-0005	E
G110-0007	E-1
G110-0008	E-2
G110-0009	E-3*
G110-0010	E-4*
G110-0012	E-5

G110 Etch Revision E	
ECO No.	CS Revision
G110-0006	F
G110-0011	M

*Note: There have been a number of Etch Rev C modules shipped that were marked CS Rev M and J these should have been marked CS Rev E3 and E4 respectively.

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM11

Title ECO DOCUMENTATION FOR THE MM11K, MM11L and MM11S Memories (Continued)			Tech Tip Number MM11-TT-10
Author G. Cable	Rev #	Cross Reference	
Approval C. Dewey	Date 12/12/72		

G231 Module

There will also be two separate types of G231 Modules in the field in the near future. For this reason it has become necessary to create two sets of engineering drawings.

The first type of G231 Module will be an Etch Revision of C. All future ECO's for this module will use a circuit schematic revision of E with a numeric digit following. Each ECO released will increment the numeric digit by one (i.e. E4, E5, E6 and etc.).

The second type of G231 Module will be an Etch Revision of E. All future ECO's for this module will use a circuit schematic revision with only an alpha character as a designator starting at CS Revision F and incrementing thru the alphabet (i.e. F, H, J, K, and etc.).

Below is a chart that shows the revisions for the two G231 Modules.

G231 Etch Revision C			G231 Etch Revision E	
ECO No.	CS Revision	Stamped on Module	ECO No.	CS Revision
G231-0001	C	C	G231-0004	F
G231-0002	N/A	N/A		
G231-0003	C-1	E		
G231-0005	1	E-1		
G231-0006	2	E-2		
G231-0007	3	3		
G231-0008	3A	3A		
G231-0009	E4	E4		

Refer to PDP 11/05 Systems Tech Tip #14 for a detailed listing and description of memory ECO's.

Title		Tech Tip	
New MM11 Option Designations		Number	
		MM11-TT-11	
AN	Processor Applicability	Author	Rev
		D. Dickhut	1
		Approval	Date
		L. Dewey	1/19/73
		Cross Reference	

This tech tip is to define the new variations of memories that are in existence and how they differ from the present MM11-L and S memories. The MM11-L and S are defined again for reference.

MM11-L (8K X 16, 900 ns)

It consists of a G110, G231 and H214 and is used on 11/05, 11/10, ME11-L and 11/40.

MM11-S (8K X 16, 900 ns)

This consists of a G110, G231, H214, and a system unit. It is used on 11/35, 11/40 to 11/45.

MM11-LP (8K X 16, memory parity)

This consists of a G109, G231 and H215 and is designed for memory parity. It plugs into a MF11-LP.

MF11-LP (Parity Option)

This is a memory parity option that consists of a nine slot backplane, one MM11-LP and one M7259 double height double width memory parity controller. The backplane can accommodate three MM11-LP's. This option is used on 11/35, 11/40 and 11/45.

MF11-L

This is a memory option that consists of a nine slot backplane and one MM11-L. It can accommodate three MM11-L and is used on 11/35, 11/40 and 11/45.

MB11-S (8K X 16)

This is a special 8K X 16 memory with a 850 ns cycle time and consists of a G110-YA, G231, and H214-YA. This memory is used only on 11/45 and exists in very limited quantities.

G109-YA (for reference only)

Module used only on PDP15 memories.

It is important to remember that the modules mentioned in the above definitions are not interchangeable with a similar looking type in another category. For example a G109 is not interchangeable with a G110 nor is a G110 interchangeable with a G110-YA. When a memory module is replaced or swapped, it should only be replaced with the exact same module type, even though another type may appear to work.

[FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bk <input type="checkbox"/>	16 Bk <input checked="" type="checkbox"/>	18 Bk <input type="checkbox"/>	36 Bk <input type="checkbox"/>	11 11


Title				Tech Tip	
1611- E and F in BA11-B/D/F Mounting Boxes				1611-TT-12	
Processor Applicability				Cross Reference	
Author	B. Dimbat	Rev	#		
Approval	C. Dewey	Date	3/14/73		

1611E and 1611F memories ca not be installed in the 11/40 box. They cannot be installed in BA11-B/D/F boxes. They can be used on the 11/60 system but only if they are installed in an 11/20 type box (BA11-E5), which has its own power supply.

1611E/F's, installed in an 11/40 box, will lose data during the power down sequence.

Title		MH11 L, S, K Memory Address Decode		Tech Tip Number		MH-TT-13	
AH	Processor Applicability			Author	John Alston	Rev	g
				Approval	B. Dimbat	Date	6/1/71
Cross Reference							

The diagram and tables supplied here are to aid F/S men when they are troubleshooting MH11L, S & K memories by relating the drive signals on the G231 with the addresses that generate them.



digital	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM11

Title MM11 L, S, K Memory Address Decode				Tech Tip Number MM11-TT-13	
AN		Processor Applicability	Author J. Alston	Rev g	Cross Reference
			Approval B. Dimbat	Date 6/1/73	

	A11=1, A10=1	A11=1, A10=0	A11=0, A10=1	A10=0, A11=0
A13=1	XS15	XS14	XS13	XS12
A12=1	E40			
A13=1	XS11	XS10	XS09	XS08
A12=0	E37			
A13=0	XS07	XS06	XS05	XS04
A12=1	E34			
A13=0	XS03	XS02	XS01	XS00
A12=0	E31			

TABLE A

		A08=1, A07=1	A08=1, A07=0	A08=0, A07=1	A08=0, A07=0
Read Cyc.	A09=1	XPRD7	XPRD6	XPRD5	XPRD4
		E46			
Write Cyc.	A09=0	XPWD3	XPWD2	XPWD1	XPWD0
		E43			
Read Cyc.	A09=1	XPWD7	XPWD6	XPWD5	XPWD4
		E46			
Write Cyc.	A09=0	XPWD3	XPWD2	XPWD1	XPWD0
		E43			

TABLE B

Title MM11, L, S, K Memory Address Decode		Tech Tip Number MM-TT-13	
All	Processor Applicability	Author J. Alston	Rev #
		Approval B. Dimbat	Date 6/1/73
			Cross Reference

TABLE C

	A05=1, A04=1	A05=1, A04=0	A05=0, A04=1	A05=0, A04=0
A06=1	YS07 _____	YS06 _____	YS05 _____ E28 _____	YS04 _____
A06=0	YS03 _____	YS02 _____	YS01 _____ E23 _____	YS00 _____

TABLE D

		A02=1, A01=1	A02=1, A01=0	A02=0, A01=1	A02=0, A01=0
Read Cyc.	A03=1	YPRD7 _____	YPRD6 _____	YPRD5 _____ E8 _____	YPRD4 _____
	A03=0	YPRD3 _____	YPRD2 _____	YPRD1 _____ E3 _____	YPRD0 _____
Write Cyc.	A03=1	YNWD7 _____	YNWD6 _____	YNWD5 _____ E8 _____	YNWD4 _____
	A03=0	YNWD3 _____	YNWD2 _____	YNWD1 _____ E3 _____	YNWD0 _____

FIELD SERVICE TECHNICAL MANUAL				Option or Designator M011
12 BK <input type="checkbox"/>	18 BK <input checked="" type="checkbox"/>	24 BK <input type="checkbox"/>	30 BK <input type="checkbox"/>	REV. 1 & OPT. 5
Title M011-D/DP Core Memory Backplane			Tech Tip Number M011-TT-14	
Processor Applicability All		Author William Apperloo	Rev g	Cross Reference
		Approval William Distefano	Date 8-5-76	

The M011-D/DP Core Memory Manual states that the G652 (mother board for the M011-D/DP) is inserted into a "Unibus Backplane". To eliminate any confusion, the "Unibus Backplane" is the modified backplanes DD11-C, D and P used on 11/04, 11/34 systems. Other Unibus Backplanes, such as 11/05, 11/35 and DD-11B expansion backplanes are not compatible with these new memory boards.


Title M011-D/DP MEMORIES FAILING HIGH CURRENT MARGINS			Tech Tip Number M011-TT-15	
Processor Applicability All		Author Jim Holdarby	Rev g	Cross Reference
		Approval Lee Mickla	Date 9-13-76	

Many reports have been received from the field concerning memories failing high current margins and module set incompatibility (i.e. unable to swap modules). Investigation has shown that the inhibit margins are not properly centered, which could cause marginal operation of the memory under conditions of high drive currents. An ECD (G235-0009) was generated to correct this problem.

Therefore, if a memory exhibits these symptoms, do a visual inspection of the G235 for the ECD. A quick check for the ECD is:

1. Place G235 component side up and fingers toward you.
2. Look at right hand side of module in large etch area (see drawing).
3. If resistor R103 (750 1W) which is across bottom of large etch is not in, ECD has not been installed.

This ECD should be installed before attempting massive module swap or option swap.



Title MM11-U/UP INSTALLATION				Tech Tip Number MM11 TT-16	
Processor Applicability		Author Jim Holderby		Rev #	
All		Approval Lee Mickle (m)		Date 12-14-76	
X				Cross Reference	

There is a problem if more than 64K of MM11-U memory is installed in the new type expansion box (EALIF) with power distribution harness 7009566. When the second H754 power supply is installed, the jumpers must be removed from the power harness. The jumpers connect P2 pin 3 to P5 pin 3 and P2 pin 14 to P5 pin 14. If these jumpers are not removed, the two(2) H754 power supplies are connected in parallel and it is possible to damage one or both regulators. The reason the jumpers are there is to allow us to install the memory backplane anywhere in the cabinet.

This information is not in the installation procedure; however, it can be found in the FDP 11/45 and 11/50 System Maintenance Manual (DEC-11-H4504-D-D) Figure 8-5, power distribution schematic.

Title MM11-E TROUBLE SHOOTING AID				Tech Tip Number MM11-TT-17	
Author MICHAEL BABCOCK		F.S. Office PITTSBURGH, PA		Date 7 JUNE 77	
Processor Applicability		Mgr./Sup.		Date	
All		Approval: JIM HOLDERBY		Date 16 JUN 77	
				Revision 0	
				Cross Reference	

THE FOLLOWING IS INTENDED AS A TROUBLE SHOOTING AID FOR THE MM11-E MEMORY

ADDRESS															
MEMORY SELECT			X SWITCH READ AND WRITE			X DRIVER READ AND WRITE			Y SWITCH READ AND WRITE			Y DRIVER READ AND WRITE			O
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	
			$P_{100} = X_{50}$			$P_{100} = X_{D0}$			$P_{100} = Y_{50}$			$P_{100} = Y_{D0}$			O PART NUMBER
			$1_{100} = X_{51}$			$1_{100} = X_{D1}$			$1_{100} = Y_{51}$			$1_{100} = Y_{D1}$			
			$2_{100} = X_{52}$			$2_{100} = X_{D2}$			$2_{100} = Y_{52}$			$2_{100} = Y_{D2}$			
			$3_{100} = X_{53}$			$3_{100} = X_{D3}$			$3_{100} = Y_{53}$			$3_{100} = Y_{D3}$			
			$4_{100} = X_{54}$			$4_{100} = X_{D4}$			$4_{100} = Y_{54}$			$4_{100} = Y_{D4}$			
			$5_{100} = X_{55}$			$5_{100} = X_{D5}$			$5_{100} = Y_{55}$			$5_{100} = Y_{D5}$			
			$6_{100} = X_{56}$			$6_{100} = X_{D6}$			$6_{100} = Y_{56}$			$6_{100} = Y_{D6}$			
			$7_{100} = X_{57}$			$7_{100} = X_{D7}$			$7_{100} = Y_{57}$			$7_{100} = Y_{D7}$			

X AND Y DRIVER SIGNALS ARE POSITIVE FOR READ; NEGATIVE FOR WRITE
(i.e. YPD0 FOR READ; YND0 FOR WRITE)

X AND Y SWITCH SIGNALS ARE NEGATIVE FOR READ; POSITIVE FOR WRITE
(i.e. XRS0 FOR READ; XPS0 FOR WRITE)

YD0 - YD3 ON G226 SLOT C03
YD4 - YD7 ON G226 SLOT F03
YS0 - YS3 ON G226 SLOT C03
YS4 - YS7 ON G226 SLOT F03

XD0 - XD3 ON G226 SLOT C02
XD4 - XD7 ON G226 SLOT F02
XS0 - XS3 ON G226 SLOT C02
XS4 - XS7 ON G226 SLOT F02

PAGE 18

FIELD SERVICE TECHNICAL MANUAL				Option or Designator MM11
12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	24 Bit <input type="checkbox"/>	MEMORY OPTION

Title MM11-E TROUBLE SHOOTING AID (CONT)		Tech Tip Number MM11-TT-17	
Author MICHAEL BARCOCK	F.S. Office PITTSBURGH, Pa	Date 6/17/77	Revision 0
Processor Applicability		My Sup.	Date
Alt 11		Approved: JIM HOLDERBY	Date 6/17/77
		Cross Reference	

LOSS OF A BYTE - TROUBLE WITH BIT 0
LOSS OF 1 (OCTAL) IN EVERY 20 (OCTAL) LOCATIONS - BAD Y DRIVER
LOSS OF 20 (OCTAL) LOCATIONS IN EVERY 200 (OCTAL) LOCATIONS - BAD Y SWITCH
LOSS OF 200 (OCTAL) LOCATIONS IN EVERY 2,000 (OCTAL) LOCATIONS - BAD X DRIVER
LOSS OF 2000 (OCTAL) LOCATIONS IN EVERY 20000 (OCTAL) LOCATIONS - BAD X SWITCH

ANY DATA BIT DROPAGE OR PICKUP IS PROBABLY CAUSED BY THE G102'S

DATA BITS 0-3	G102 SLOT D03
DATA BITS 4-7	G102 SLOT D02
DATA BITS 8-11	G102 SLOT E03
DATA BITS 12-15	G102 SLOT E02

ADDRESS BIT 0 - BYTE SELECT DURING DATOS

ADDRESS BITS 1-3			READ DRIVER	WRITE DRIVER	
3	2	1			
0	0	0	YPD0	YND0	
0	0	1	YPD1	YND1	SWITCH/DECODER A
0	1	0	YPD2	YND2	G226 SLOT C03
0	1	1	YPD3	YND3	
1	0	0	YPD4	YND4	
1	0	1	YPD5	YND5	SWITCH/DECODER B
1	1	0	YPD6	YND6	G226 SLOT F03
1	1	1	YPD7	YND7	

ADDRESS BITS 4-6					
6	5	4			
0	0	0	YNS0	YPS0	
0	0	1	YNS1	YPS1	SWITCH/DECODER C
0	1	0	YNS2	YPS2	G226 SLOT C03
0	1	1	YNS3	YPS3	
1	0	0	YNS4	YPS4	
1	0	1	YNS5	YPS5	SWITCH/DECODER D
1	1	0	YNS6	YPS6	G226 SLOT F03
1	1	1	YNS7	YPS7	

CONFIDENTIAL
This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only.
For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 19	Page Revision 0	Publication Date JUNE 1977
----------------	------------------------	-----------------------------------

PRINTED IN U.S.A.

Title MM11-E TROUBLE SHOOTING AID (CONT)		Tech Tip Number MM11-TT-17	
Author MICHAEL SABCOCK	F.S. Office PITTS., PA	Date 6/17/77	Revision 0
Processor Applicability		Mgr./Sup.	Date
All 11		Approval: JIM HOLDERBY	Date 6/17/77
		Cross Reference	

ADDRESS BITS 7-9

9	8	7			
0	0	0	XPD0	XND0	
0	0	1	XPD1	XND1	SWITCH/DECODER A
0	1	0	XPD2	XND2	G226 SLOT C02
0	1	1	XPD3	XND3	
1	0	0	XPD4	XND4	
1	0	1	XPD5	XND5	SWITCH/DECODER B
1	1	0	XPD6	XND6	G226 SLOT F02
1	1	1	XPD7	XND7	


ADDRESS BITS 10-12

12	11	10			
0	0	0	XNS0	XPS0	
0	0	1	XNS1	XPS1	SWITCH/DECODER C
0	1	0	XNS2	XPS2	G226 SLOT C02
0	1	1	XNS3	XPS3	
1	0	0	XNS4	XPS4	
1	0	1	XNS5	XPS5	SWITCH/DECODER D
1	1	0	XNS6	XPS6	G226 SLOT F02
1	1	1	XNS7	XPS7	

M M M I I - E

MM11-E/F PARTS BREAKDOWN

7006405	- Logic Frame
7006468	- MM11-E Wired assembly
70007263	- MM11-F Wired assembly
G102	- Sense Inhibit Card
G103	- Memory Levels & Gates
G225	- X-Y Current Generator
G226	- X-Y Current Generator
H207	- 4K 16 Bit Core Memory Stack
M109	- Device Select
M729	- MM11-E Control Logic
M1091	- Device Select
M7290	- Control Logic & Timing
MM11-E	- 4K Single Memory Unit
MM11-EX	- 4K Interleaved
MM11-F	- 4K Single Memory Unit
MM11-FP	- Single Parity Memory Unit
MM11-FX	- Interleaved Memory (jumpers)



Engineering Change Order Log

ECO SYNOPSIS pages are updated and published continuously in conjunction with the issuance of ENGINEERING CHANGE ORDERS for all DEC products and are available upon subscription form.

DIGITAL EQUIPMENT CORPORATION
FIELD SERVICE INFORMATION CENTER
MAYNARD, MASSACHUSETTS 01754

EQUIPMENT CORPORATION
MAYNARD, MASSACHUSETTS

ECO SYNOPSIS FOR LOGIC OR OPTION

PDP-11 MEMORY **MM11-E**

PRODUCT LINE	PUBLICATION DATE OF THIS SYNOPSIS PAGE	PAGE REVISION
PDP-11	JULY 1976	8

ECO NO.	LOGIC OR OPTION SERIAL NO. AFFECTED	FIELD CODE	SYNOPSIS
MM11-E 00001	MM11-E	H	JAN 76 - CHANGES STACK MINGE TOLERANCE AND ADDS A FLATNESS SPECIFICATION.
MM11-E 00002	MM11-E 110-180	D	JAN 76 - MAKES CORRECTIONS TO THE WIRE LIST.
MM11-E 00003	MM11-E 110-180	D	JAN 76 - ADDS CURRENT LOOPS FOR X AND Y CURRENT MEASUREMENTS AND SCOPING. UPDATES THE LIST OF MANUALLY INSTALLED WIRING.
MM11-E 00004	MM11-E	D	JAN 76 - UPDATES THE MM11-E PRINT SET.
MM11-E 00005	N.A.	D	JAN 76 - CORRECTS A DRAWING WHICH WAS DRAWN IN REVERSE. ADDS CLARIFICATION NOTES.
MM11-E 00006	MM11-E 110-239	D	FEB 76 - ADDS TWO WIRES WHICH WERE PREVIOUSLY OMITTED FROM THE WIRE LIST.
MM11-E 00007	MM11-E	H	FEB 76 - CHANGES THE SPECIFICATION FOR THE MEMORY MINGE. SPECIFIES THE USE OF SELF EXTINGUISHING PLASTIC FOR MM11-E FABRICATION.
N789 00001	ALL N789	D	MAR 76 - REVISES SEVERAL DESIGN CONSIDERATIONS; CHANGES THE ETCH LAYOUT AND SEVERAL COMPONENTS. MODULE STATUS - UNRELEASED. N789 CIRCUIT SCHEMATIC REVISION A ETCHED BOARD REVISION B
8886 00003	8886	D	MAR 76 - ADDS BIDDERS TO CLAMP OUTPUT VOLTAGE SPIRES WHICH COULD EXCEED THE TRANSISTOR BREAKDOWN RATING. MODULE STATUS - UNRELEASED. 8886 CIRCUIT SCHEMATIC REVISION C

ECO NO.	LOGIC OR OPTION SERIAL NO. AFFECTED	FIELD CODE	SYNOPSIS
8102 00002	PDP-11	F	MAR 76 - REPLACES THE 8881 IC WITH A 74MS11 TO INCREASE SPEED. THIS MODULE CANNOT BE REWORKED IN THE FIELD. (ERROR CORRECTED BY ECO 8102-00003) 8102 CIRCUIT SCHEMATIC REVISION B ETCHED BOARD REVISION D
8103 00002	ALL PDP-11	F	MAR 76 - REPLACES SN7410M IC WITH SN7410N TO INCREASE SYSTEM SPEED. THE MODULE CANNOT BE REWORKED IN THE FIELD. 8103 CIRCUIT SCHEMATIC REVISION B
8108 00003	PDP-11	F	APR 76 - CORRECTS AN ERROR IN ECO 8102-00003; CHANGES 100 OHM RESISTORS TO 75 OHMS. 8108 CIRCUIT SCHEMATIC REVISION B ETCHED BOARD REVISION D
MM11-E 00008	MM11-E	P	APR 76 - CORRECTS DIMENSIONS ON THE ETCHED BOARD DRAWING TO MEET STANDARDS.
MM11-E 00009	N.A.	P	APR 76 - CHANGES WIRING AND TUBING REFERENCES ON THE PARTS LIST.
8103 00004	ALL PDP-11	F	APR 76 - CHANGES R17 FROM A 100 OHM TRIMPOT TO A 500 OHM TRIMPOT. 8103 CIRCUIT SCHEMATIC REVISION C
8616 00001	N.A.	D	APR 76 - DELETES THE MODULE HANDLE FROM THE 8616 PARTS LIST AND ADDS IT TO THE MEMORY STACK PARTS LIST. 8616 CIRCUIT SCHEMATIC REVISION B
8616 00002	8616	D	MAY 76 - INTERCHANGES THE POSITIONS OF THEWISTERS R71 AND RESISTOR R1. 8616 CIRCUIT SCHEMATIC REVISION C
MM11-E 00010	N.A.	P	MAY 76 - ADDS A MODULE CLIP HOLDEN PART NUMBER AND ITS DESCRIPTION TO THE PARTS LIST.
MM11-E 00011	MM11-E	P	MAY 76 - ADDS MM11-E ALIGNMENT PROCEDURE TO THE PRINT SET.
MM11-E 00012	MM11-E	D	MAY 76 - CHANGES A HOLE SIZE AND ADDS TWO OTHERS FOR THE 8616.

FIELD CODES

- F - Field action may be required
- D - Design ECO
- P - Part or sub Lot change
- H - Historical ECO

SYNOPSIS

- > - ECO applicable to future production

ECO CATEGORIES

- 01 - Change in spec. or drawing. (P, H, D, F, S)
- 02 - Change for design and manufacturing (D)
- 03 - Change for assembly (P)
- 04 - Change for test (P)
- 05 - Change for test (P)
- 06 - Change for test (P)
- 07 - Change for test (P)
- 08 - Change for test (P)
- 09 - Change for test (P)
- 10 - Change for test (P)

MASTER DRAWING LIST REVISIONS	
REV	ECO NUMBER
A	MM11-E-00002
B	MM11-E-00003
C	MM11-E-00004
D	MM11-E-00005
E	MM11-E-00006
F	PDP11-00004

WIRE LIST REVISIONS	
REV	ECO NUMBER
A	MM11-E-00002
B	MM11-E-00004

LEGEND

- F - Field action may be required
- D - Design ECO
- P - Part or sub Lot change
- H - Historical ECO

SYNOPSIS

- > - ECO applicable to future production

ECO CATEGORIES

- 01 - Change in spec. or drawing. (P, H, D, F, S)
- 02 - Change for design and manufacturing (D)
- 03 - Change for assembly (P)
- 04 - Change for test (P)
- 05 - Change for test (P)
- 06 - Change for test (P)
- 07 - Change for test (P)
- 08 - Change for test (P)
- 09 - Change for test (P)
- 10 - Change for test (P)

MASTER DRAWING LIST REVISIONS	
REV	ECO NUMBER
H	MM11-E-00009
J	MM11-E-00010
K	MM11-E-00011

WIRE LIST REVISIONS	
REV	ECO NUMBER

Engineering Change Order Log

ECO SYNOPSIS pages are updated and published continuously in conjunction with the issuance of ENGINEERING CHANGE ORDERS for all EOC products and are available upon subscription form:

DIGITAL EQUIPMENT CORPORATION
FIELD SERVICE INFORMATION CENTER
MAYNARD, MASSACHUSETTS 01754



ECO SYNOPSIS FOR LOGIC OR OPTION

POP-11 MEMORY **MM11-E**

PRODUCT LINE	PUBLICATION DATE OF THIS SYNOPSIS PAGE	PAGE REVISION
POP-11	APRIL 1971	4

ECO NO.	LOGIC OR OPTION SERIAL NO.'S AFFECTED	FIELD CODE	SYNOPSIS
			REFERENCE ECO 6100-0003
6100 0003	ALL MM10 MM11-1	P	JUN 70 - CHANGES CIRCUITRY TO PROVIDE -6.0VDC INSTEAD OF -5VDC FOR THE SENSE AMPLIFIERS. ADDS A HEAT SINK TO J4 TO PROVIDE ADEQUATE HEAT DISSIPATION. BOTH OF THESE CHANGES ARE ONSCREEN FOR IMMEDIATE BENEFIT IN THE ME10 UNIT ARE TO BE PHASED IN ON THE MM11-E. CHANGES CIRCUITRY TO SPEED UP TURN-OFF TIME FOR THE STACK DISCHARGE CIRCUITS. THIS CHANGE IS TO BE PHASED IN ON BOTH THE ME10 AND MM11-E. THE MANUAL CAN BE RETURNED IN THE FIELD.
6220 0003	ALL MM11-E	P	JUL 70 - REDUCES THE VALUE OF RESISTOR R22 TO 2.2K TO SPEED UP STABILIZATION OF THE A/V CURRENT REFERENCE VOLTAGE. SOLVES THE PROBLEM OF LOSS OF MEMORY DATA DURING POWER UP ON POWER UNITS.
MM11-E 00013	MM11-E	A	JUL 70 - SPECIFIES A REWORKING OF THE MODULE HOLDERS.
MM11-E 00014	MM11-E 100-953	P	AUG 70 - DELETES CONFLICTING REFERENCES TO THE IC'S ON THE 6102 FROM THE MM11-E-04 LOGIC PRINT.
MM11-E 00015	MM11-1 100-953	P	SEP 70 - CONNECTS THE SIGNAL BUS "AC LO L" FROM THE POWER BUS TO THE UNIBUS. CONNECTS THE SIGNAL BUS "UC LO L" FROM THE POWER BUS TO THE UNIBUS. THESE CHANGES PROVIDE PROPER OPERATION OF THE POWER FAIL OPTION IN MULTIPLE BOX SYSTEMS. THIS ECO MUST BE INSTALLED IN CONJUNCTION WITH ECU'S 9030-0001, 9011-0007, AND 900475-0000 AND IS APPLICABLE TO ALL MULTIPLE BOX SYSTEMS.
MM11-E 00016	ALL MM11-1 SHIPPED JULY- DEC., 1970	P	AUG 70 - PROVIDES A COPY OF THE 24-50 WIRE TABLE AND INSTALLATION FOR CORRECTING IMPROPERLY WIRED UNITS WHICH WERE SHIPPED BETWEEN JULY AND DECEMBER OF 1970. SYMPTOMS OF THIS MEMORY WIRING PROBLEM INCLUDE DATA ERRORS, LOW MEMORY MARGINS, AND NON-INTERCHANGEABILITY OF 5100 MODULES.

LEGEND

FIELD CODE

- P - Part change only as required
- D - Design ECO
- F - Part or Draw List change
- B - Mechanical ECO

SYNOPSIS

- > - ECO applicable to future production

ECO CHANGES

- Changes are noted within the synopsis. *001, *002, **003
- 01 - Change for future and existing units
- 02 - Change for existing units
- 03 - Change for on site later
- 04 - Change for on site later
- 05 - Change for on site later
- 06 - Change for on site later
- 07 - Change for on site later
- 08 - Change for on site later
- 09 - Change for on site later
- 10 - Change for on site later

MASTER DRAWING LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
L	MM11-E-00013		
M	MM11-E-00014		
P	MM11-E-00015		
N	MM11-E-00016		

WIRE LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
C	MM11-E-00015		

JUN 7 1971

ECO NO.	LOGIC OR OPTION SERIAL NO.'S AFFECTED	FIELD CODE	SYNOPSIS
MM11-E 00017	MM11-1 AS NEAR AS	P	JAN 71 - CORRECTS THE TEST PROCEDURE TO SPECIFY CHANGING THE SENSE SENSING FROM 210 MSEC TO 200 MSEC TO IMPROVE MEMORY PERFORMANCE. ECU MM11-E-0002 SUPERSEDES THIS ECO SINCE SENSE SENSING IS NOW 210 MSEC. SOME TIMES CHANGES WAS TOO HIGH FOR OPTIMUM PERFORMANCE AND ADJUSTING THE SENSE SENSING. CHANGES THE JUNE LIST. UPDATES THE BLOCK SCHEMATIC TO REFLECT CHANGES MADE TO THE 9120 CIRCUIT SCHEMATIC. UPDATES WIRING AND FLOW DIAGRAMS.
MM11-E 00018	MM11-1	A	JAN 71 - OVERTS BLOTTING OF THE 900 PIN BLOCKS DUE TO ELIMINATE THEIR OCCASION OUT WHEN FROM BIF CARDS ARE INSERTED AND REMOVED.
MM11-E 00019	M.A.	P	MAR 71 - UPDATES DOCUMENTATION TO INCLUDE THE 91001 MODULE. UPDATES PRINTS TO INCLUDE INSTRUCTIONS FOR INTERLEAVING MEMORIES.
MM11-E 00020	MM11-1 WITH ECU MM11-E-00017	P	MAR 71 - THIS ECO REVISIONS THE SENSE SENSING SPECIFICATION OF ECO MM11-E-00017. CORRECTS THE TEST PROCEDURE TO SPECIFY SENSING THE SENSE AT 210 MSEC. SENSING IS AT 200 MSEC AS SUGGESTED IN ECU MM11-E-00017 IS TOO LATE FOR OPTIMUM PERFORMANCE.
			<p>MM11E-00021 CODE P ML Y MAY 71 PROBLEM: Packaging instructions for the POP 11 memory unit are not included in the print set. CORRECTION: Add packaging instructions to MM11-E drawing table list in plant effectively. Documentation change only.</p> <p>MM11E-00022 CODE DP ML W MAR 71 PROBLEM: Under some conditions when other options are placed along with an MM11-E they fail to operate correctly. CORRECTION: Install a module protection plate. In-plant effectively: Rework all MM11-E's as required. Field effectively: All MM11-E's as required. Time To Install And Test 10 Hour. Ed Controls PCU/Prints And Parts.</p> <p>MM11E-00023 CODE P ML Y APR 71 CORRECTION: Update test procedure. In-plant effectively: Documentation change only.</p> <p>MM11E-00024 CODE V ML AA WL K MAY 71 PROBLEM: Signal signals and TIME have too much noise on them. CORRECTION 1: Install twisted pair wiring for these signals. PROBLEM 2: READ #1 signal has too many leads on it. CORRECTION 2: Develop another READ #1 signal to share the load. In-plant effectively: Rework immediately. Field effectively: Rework all MM11-E. If revision K is created: Time To Install And Test 10 Hour. Ed Controls PCU/Prints Only.</p>

LEGEND

FIELD CODE

- P - Part change only as required
- D - Design ECO
- F - Part or Draw List change
- B - Mechanical ECO

SYNOPSIS

- > - ECO applicable to future production

ECO CHANGES

- Changes are noted within the synopsis. *001, *002, **003
- 01 - Change for future and existing units
- 02 - Change for existing units
- 03 - Change for on site later
- 04 - Change for on site later
- 05 - Change for on site later
- 06 - Change for on site later
- 07 - Change for on site later
- 08 - Change for on site later
- 09 - Change for on site later
- 10 - Change for on site later

MASTER DRAWING LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
M	MM11-E-00017		
D	MM11-E-00018		
F	MM11-E-00019		
I	MM11-E-00020		

WIRE LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
N	MM11-E-00017		

JUN 7 1971

FCCO'S

DWG LOC.
B-6


B-4

M920
B01

M920
B04

M920
B01

M920
B04



ECO # MM11E-00015

D-36-MM11-E-09

NEW
REV.
A


DWG NO	REV LET	NO OF SHEETS	TITLE
D-IC-MM11-E-09	A	1	I/O CONNECTORS
K-WL-M11-E-07	BC	2	WIRE LIST

ECO # MM11E-00015


A-ML-MM11E

NEW
REV.
P


DWG LOC.
D-4




C-4+3



B-5




B5+6



D-TD-MM1E-08

ELO # MM1E-00016

LENGTH SHOULD BE A MAXIMUM OF 2 1/4 INCHES. CHECK DRAWINGS FOR LENGTH AND FOR HOW LOOPS SHOULD BE DRESSED INTO LOGIC.



ECO# MM11E-00016 D-AD-7006468-0-0

NEW
REV
C

DWG NO.	REV LET
D-AD-7006468-0-0	BC
A-PL-7006468-0-0	BC
D-TD-MM11-E-18	AB

ECO# MM11E-00016

A-ML-MM11-E

NEW
REV.
N

ENGINEERING CHANGE ORDER

ECO NO.
MM11E-00017
Sheet 1 of 4

ORIGINATOR RICHARD MANTON DATE 12/15/70	EXT. 2005	RECEIVED CHG. DATE 12/22/70	ISSUED ECO DATE 1-22-71	FINAL RELEASE DATE	DISCRETE PROJECT NUMBER 11 07602
--	--------------	--------------------------------	----------------------------	--------------------	-------------------------------------

EQUIPMENT AFFECTED

TYPE CHANGE	UNIT TO BE CHANGED	CHECKLIST	YES	NO
ELECTRICAL <input checked="" type="checkbox"/>	MM11-E	SHOP MODEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MECHANICAL <input type="checkbox"/>	PRODUCT LINES	SYSTEMS PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MODULE <input type="checkbox"/>		DIAGNOSTICS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SUBASSEMBLY <input type="checkbox"/>		TECHNICAL PUB.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
NEG. PROCEDURE <input type="checkbox"/>	PDP11	TEST PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
TEST INFORMATION		TESTER	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SERIAL #		MFG./FIELD PROCEDURE	<input type="checkbox"/>	<input checked="" type="checkbox"/>
BY		PACKAGING INSTRUCTIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		TOOLING	<input type="checkbox"/>	<input checked="" type="checkbox"/>

BREAK IN POINT				SIGNIFICANCE	
SYSTEM	MODULE/OPTION	FIELD	REWORK	CODE	
	MM11-E	DISTRIBUTED FOR FIELD SERVICE INFORMATION ONLY		05	REQ. TO MEET SPECIFICATION <input type="checkbox"/>
					PROD. IMPROVEMENT <input checked="" type="checkbox"/>
					CUSTOMER/FIELD REQ. <input checked="" type="checkbox"/>
					FACILITATE MFG. <input type="checkbox"/>
					DRAWING CORRECTION <input type="checkbox"/>
					VENDOR <input type="checkbox"/>

PROBLEM

1. WANTED TO IMPROVE MEMORY PERFORMANCE. STROBE 210 NS WAS TOO EARLY FOR OPTIMUM PERFORMANCE. SOME TIMES CURRENT WAS TOO HIGH FOR OPTIMUM PERFORMANCE WHEN ADJUSTING THE REFERENCE VOLTAGE.
2. WIRE LIST WAS NOT CHANGED ACCORDING TO ECO # MM11E-00015.
3. BLOCK SCHEMATIC DOES NOT REFLECT CHANGES OF M729 CIRCUIT SCHEMATIC
4. TIMING AND FLOW DIAGRAM NEEDS TO BE UPDATED.
5. WRITING IN MARGIN

CORRECTION

1. CHANGE TEST PROCEDURE TO IMPROVE MEMORY PERFORMANCE.
2. CORRECT WIRE LIST ACCORDING TO SUBMITTED ADD/DELETE SHEET.
3. UPDATE BLOCK SCHEMATIC PER ATTACHED MARKED UP PRINT.
4. UPDATE TIMING AND FLOW DIAGRAM AS INDICATED.
5. REMOVE WRITING FROM MARGIN.

BY R. DEWITT ENG. MGR
 FOR D. J. L. FIELD SERVICE (ADVISORY) J. BIZYSKI


**ENGINEERING CHANGE ORDER
DOCUMENT & MATERIAL
CHANGE**

ECO NO.
MM11E-00017
Sheet 2 of 4

ITEM	PART NO.	OLD REV	NEW REV	(PART NAME) DESCRIPTION OF CHANGE	DISP CODE
1	A-NL-MM11-E	P	R	(MASTER LIST) UPDATE REVISION LEVEL ON THE FOLLOWING DRAWINGS: D-BS-MM11-E-05 FROM A TO B K-WL-MM11-E-07 FROM C TO D D-TD-MM11-E-08 FROM B TO C A-SP-MM11-E-11 FROM O TO A	06
2	D-BS-MM11-E-05	A	B	(BLOCK SCHEMATIC) SEE MARKED PRINT THIS ECO.	06
3	K-WL-MM11-E-07	C	D	(WIRE LIST) SEE ADD/DELETE SHEET THIS ECO.	06
4	D-TD-MM11-E-08	B	C	(TIMING DIAGRAM) DELETE CHECK RACE COND. IN MARGIN. INCREASE TIME AND FLOW IN DISZ BEFORE 650NS. INCREASE TIME AND FLOW IN CINE BEFORE 350 NS.	06
5	A-SP-MM11-E-11	-	A	(ENGINEERING SPECIFICATION) DELETE FROM PARA. 11.0 210 NS . ADD 220NS. ADD TO PARA. 13.4- IF THE MARGIN IS GREATER THAN 1.0V SET VKY AT 0.5 BELOW THE FAILING HIGH END POINT. (EXAMPLE IF MARGINS ARE 0.4 TO 1.0V, SET AT 1.3V= 1.0-0.5)	06

DISPOSITION CODES

Use up Present Stock	01	Retrofit to Stock-In	05
Use Present Stock until New Stock Available	02	Documentation Change Only	06
Rework all Material	03	New Item Purchase	07
Rework until New Stock Available	04	New Item in Stock	08
		New Item on Order	09
		Return	00



ECO# MM11E-00017

0-BS-MM11-E-05

NEW
REVB

ORIGINATOR RICHARD MAJION DATE 3/9/71 EXT. 2005		ENGINEERING CHANGE ORDER		ECO NO. NM11B-00020 Sheet 1 of 3
		RECEIVED CHG. DATE 3/24/71	ISSUED ECO DATE 3-26-71	FINAL RELEASE DATE 4-13-71
DISCRETE PROJECT NUMBER 11 07602				

EQUIPMENT AFFECTED

TYPE CHANGE	UNIT TO BE CHANGED	CHECKLIST	YES	NO
ELECTRICAL <input checked="" type="checkbox"/>	NM11B	SHOP MODEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MECHANICAL <input type="checkbox"/>	PRODUCT LINES	SYSTEMS PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MODULE <input type="checkbox"/>		PDP11	DIAGNOSTICS	<input type="checkbox"/>
SUBASSEMBLY <input type="checkbox"/>		TECHNICAL PUB.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
MFG/FIELD PROCEDURE <input type="checkbox"/>		TEST PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
TEST INFORMATION		TESTER	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SERIAL #		MFG/FIELD PROCEDURE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
BY		PACKAGING INSTRUCTIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		TOOLING	<input type="checkbox"/>	<input checked="" type="checkbox"/>

BREAK IN POINT				SIGNIFICANCE	
SYSTEM	MODULE/OPTION	FIELD	REWORK	CODE	
FIELD SERVICE CULD F	NM11B	DISTRIBUTED FOR FIELD SERVICE INFORMATION ONLY		06	REQ. TO MEET SPECIFICATION <input type="checkbox"/>
					PROD. IMPROVEMENT <input checked="" type="checkbox"/>
					CUSTOMER/FIELD REQ. <input type="checkbox"/>
					FACILITATE MFG. <input type="checkbox"/>
					DRAWING CORRECTION <input checked="" type="checkbox"/>
					VENDOR <input type="checkbox"/>

REASON

- 1) WANTED TO IMPROVE MEMORY PERFORMANCE. STROBE AT 220 NS AS SUGGESTED IN ECO NM11B-00017 WAS TOO LATE FOR OPTIMUM PERFORMANCE
- 2) PAR 12.0 NM11B TEST PROCEDURE INCORRECT. V THRESHOLD SET TO -5.3V IS TOO LOW.

CORRECTION

- 1) CHANGE STROBE SETTING AS STATED IN PARAGRAPH 11.0 FROM 220 NS TO 210 NS
- 2) CHANGE TEST PROCEDURE . SET V THRESHOLD AT -5.2V

NOTE: BY ECO NM11B-00017 PROBLEM 1. IF THE CORRECTION FOR PROBLEM (1) IN ECO NM11B-00017 WAS NOT PERFORMED IT WILL NOT BE NECESSARY TO IMPLEMENT CORRECTION (1) OF THIS ECO.

APPROVAL

DESIGN ENGINEER R. DURANT 3/2/71 ENG. MGR. _____

PRODUCTION ENGINEER DOE CALL 3/3/71 FIELD SERVICE _____

CHIEF ENGINEER _____ (ADVISORY) J. BUKYNSKI

**ENGINEERING CHANGE ORDER
DOCUMENTATION MATERIAL**

ECO NO.
1011B-00020
Sheet 2 of 3

ITEM	DOCUMENTATION PART NUMBER	OLD REV	NEW REV	DESCRIPTION OF CHANGE	DISP CODE
1	A-ME-1011-E	T	U	(MASTER LIST) UPDATE REVISION LEVEL OF ITEM 3 THIS ECO	06
2	A-ME-1011-EX	-	A	(MASTER LIST) SAME CHANGE AS ITEM 1 THIS ECO	06
3	A-SP-1011E-11	A	B	(TEST PROCEDURE) SHEET 4 OF 5: DELETE 220 NS IN PARAGRAPH 11.0 ADD 210 NS DELETE -5.3V IN PARAGRAPH 12.0 ADD -5.2V UPDATE REVISION LEVEL ON ALL SHEETS	06

DISPOSITION CODES

Use up Present Stock	01	Revert to Stock-In	05
Use Present Stock until New Stock Available	02	Documentation Change Only	06
Rework of Material	03	New Item Purchase	07
Rework until New Stock Available	04	New Item in Stock	08
		New Item on Order	09
		Return	00

DRA 112A

SEE REVERSE SIDE FOR INSTRUCTIONS

FIELD SERVICE NOTES:

ECO MM115-00020
Page 1 of 1

C LEVEL OF URGENCY code

The ECO number will be posted to the EDP file with this LOU code replacing the lead # - "A"= Mandatory, High Priority
"B"= Mandatory "C"= Applicable if symptoms are present
"D"= Low Priority "D"= Product Improvement, Optional

Yes This ECO is NO CHARGE TO CUSTOMER - All DDC installation labor and materials are to be reported under a "W" charge code.

No This ECO is WARRANTY APPLICABILITY - It is to be installed at no charge for warranty and maintenance contract customers in accordance with the technical effectivity, otherwise at customer expense.
Charges - Documentation \$ N/A, Parts \$ N/A
DDC on-site labor \$ N/A. (minimum per call billing applies)
(* parts prices not available at the time of Speco release)

F FIELD DISTRIBUTION CODE

"F"= Immediate Speco distribution to all field offices
"DF"= No general Speco distribution, only to offices where equipment is located (less than 25 units in the field)

No UNCONDITIONAL ECO - General distribution kits will include Field Installation Orders, Specos, Prints, and Parts.

Yes CONDITIONAL ECO - General distribution will include Field Installation Orders only. Prints and parts must be ordered from FSIC as required.

No Parts availability delay expected _____.

Yes The REQUIREMENT TO MEET SPECIFICATION is applicable retroactively to equipment in the field.

NOTE:



ENGINEERING
CHANGE ORDER 823

ORIGINATOR Richard Nanion
TEL EXT 2005 DATE 3/13/72
DESC PROJ NO. 11 07602
COST CENTER NO. 392
A.R.

ECO NO. MM11E-00028
SHEET 1 OF 3
DATE RECEIVED 3-16-72
FIRST ISSUE 3-20-72
FINAL ISSUE

PROBLEM
Under some conditions when other options are placed along side an MM11/E they fail to operate correctly.

UNIT TO BE CHANGED
MM11/E
Memory

REP CODE 34

CORRECTION
Install a module protection plate.

OPTIONS AFFECTED
MM11/E

BREAK-IN/EFFECTIVITY
*Install module protection plate only when problems occur.

PRODUCT LINES AFFECTED
PDP11/20

ITEM NO.	DOCUMENT/PART NO.	OLD REV	NEW REV	ORIG CODE	DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED
1.	C-DI-MM11-E-01	0	E	06	(Drawing Index Memory) Change per this ECO.	<input type="checkbox"/> MODEL <input type="checkbox"/> DIAGNOSTICS <input type="checkbox"/> TECH MANUAL <input type="checkbox"/> TESTER <input type="checkbox"/> TEST PROG <input type="checkbox"/> TOOLING <input type="checkbox"/> PLO INST <input type="checkbox"/> ENG SPEC <input type="checkbox"/> PURCH SPEC
2.	7408490	-	-	07	(Module Protection Plate) Add quantity of 1 to drawing index.	<input type="checkbox"/> CUSTOMER CHG <input checked="" type="checkbox"/> PRODUCT LINE CHG
3.	A-ML-MM11-E	V	W	06	Update per item 1.	<input type="checkbox"/> ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE ORDER PR MODEL <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

DISPOSITION CODES

- 00 - RETURN TO STOCK
- 01 - (DELETED)
- 02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PLEASE DO NOT ORDER IMMEDIATELY (RESTOCK))
- 03 - (ON ORDER)
- 04 - (DELETED)
- 05 - DOCUMENT CORRECTION
- 06 - NEW ITEM (THIS ASS -LY)
- 07 - NEW ITEM (THIS ASS -LY)
- 08 - SCRAP IMMEDIATELY

APPROVAL SIGNATURES

DESIGN ENGINEER *Rete Durant*
 ENG MGR (OPT) _____
 FIELD SERVICE (OPT) _____
 CHIEF ENGR (MODULES ONLY) *Rete*



FIELD CHANGE ORDER

FCO MM1E - D 0022
PAGE 2 OF 1

DATA PROCESSING AND SEC-000-LES WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO.

- LEVEL OF URGENCY CODE
- A MANDATORY - HIGH PRIORITY
- B MANDATORY
- C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYSTEMS ARE PRESENT
- D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE, OR SYSTEMS ARE PRESENT
- E PRODUCT IMPROVEMENT - OPTIONAL - LOW PRIORITY

FIELD SERVICE
MM1-E Memory Assembly

FIELD SERVICE IS AUTHORIZED IN 5 % OF UNITS DEFINED ABOVE

NO CHARGE TO CUSTOMER - ALL SEE INSTALLATION LABOR AND MATERIAL ARE TO BE SUPPLIED UNDER A "P" CHARGE CODE.

EXTENDED APPLICABILITY - THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE ORIGINAL EFFICIENCY ADVICE, OTHERWISE AT CUSTOMER EXPENSE.

EXEMPTED FROM: PARTS 0, 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100.

SEE SERVICE MANUAL FOR THE FCO IS INSTALLED BY THE USER. THE USER SHALL BE RESPONSIBLE FOR INSTALLATION DURING REGULAR BUSINESS HOURS OF INSTALLATION OUTSIDE OF REGULAR BUSINESS HOURS IS CHARGED. THE LATEST EDITION OF SERVICE MANUAL WILL APPLY.

SECURITY PROJECT NUMBER
(FOR FIELD SERVICE REPORTS)

AVAILABILITY DELAY	NO PARTS
DATE	DATE

ESTIMATED DOWNTIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

FIELD OFFICE FOR INFORMATION ONLY

F. MANDATORY FCO DISTRIBUTION TO ALL THE FIELD OFFICES

G. MANDATORY FCO DISTRIBUTION TO GENERAL PRODUCT SUPPORT AND TO OFFICE WHERE PROJECT EQUIPMENT IS LOCATED.

LAST PREVIOUS FCO G020, G016, G15
RELATED OR PREDECESSOR FCO'S

FCO BY NUMBER

THIS WILL REPLACE OR SUPPLEMENT OF FCO'S AS DEFINED BELOW IN ACCORDANCE WITH THE DISCONTINUATION FILE.

THIS FCO WILL REPLACE OR SUPPLEMENT OF FCO'S AS DEFINED BELOW IN ACCORDANCE WITH THE DISCONTINUATION FILE.

- MAJOR CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

CONTENTS OF DISCONTINUATION FILE		THIS FCO WILL BE DISTRIBUTED FOR ALL UNITS IN THE DISCONTINUATION FILE IN THE SERVICE STATUS LOGS	
FCO	FCO	FCO	FCO
FCO	FCO	FCO	FCO

VERIFICATION CHANGES

PARTS CHANGES ARE TO BE MADE MANUALLY IN RED AND OTHER FCO REVISED PARTS WILL BE SUPPLIED ONLY WITH SPECIAL REQUEST

PARTS REQUIRED
Q1 74-08490 Module Protection Plate

INSTALLATION AND TEST PLAN

- Carefully install module protection plate per FCO instructions. This requires insertion of the plate under existing wire runs which are easily broken.
- Run maindeck or other programs whose failure indicated the need for this FCO to be implemented. They should now function correctly.


NOTE

FIELD SERVICE APPROVAL
Charles Dewey

CDK
3/20 3/24 (0) 3/24 75

ECO MM115-00022
MMHF REWORK SHEET SHEET 2 OF 2

1. LOOSEN 2 SCREWS AT POINTS A, CARE SHOULD BE USED AT ALL TIME SO, THAT NO WIRES WILL BE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE END LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINTS B.
3. TIGHTEN SCREWS.



	TITLE	DESIGN	GRAPHIC DESCRIPTION
	ALYON FVOTDO LUG NO. CITE	NO. LOC	

ORIGINATOR R. Manion 1-3
 T. E. 2:05 DATE 5-6-72
 DDC P. J. NO. D-96-6122
 COST CENTER NO. 392

ECO
 SHEET 1
 DATE RECEIVED 5-9-72
 FIRST ISSUE 5-11-72
 FINAL ISSUE 6-24-72

PROBLEM 1. STROBE Signals and TURN have too much noise on them.
 2. Read H signal has too many loads on it.

UNIT TO BE CHANGED
 MM11-E

DEF CODE 03

CORRECTION
 1. Install twisted pairs for these signals.
 2. Develop another Read H signal to share the load.

OPTIONS AFFECTED
 MM11-E

BREAKEFFECTIVITY All MM11-E's shipped after May 12 will have this ECO.
 Rework M71. If necessary, all MM11-E's with this
 ECO, must be with ECO # 9.

PRO. T. L. YES
 AFFECTED
 PDP-11/45
 PDP-11/20
 PDP-11/45

ITEM NO.	DOCUMENT/PART NO.			DESCRIPTION OF CHANGE	LOCATION
1	E-WL-MM11-E-01	D	E	06 Wire List Update	<input type="checkbox"/> MODEL
2	D-AB-7006468-0-0	D	E	06 Wire Ass'y MM11-E See final release print.	<input type="checkbox"/> DIAGNOSTICS
3	D-DB-MM11-E-03	A	B	06 Core Memory stack (2 sheets) See final release print.	<input type="checkbox"/> TECH MANUAL
4	A-041-MM11-E-0	Z	AA	06 UPDATE PRINT PER THIS ECO.	<input checked="" type="checkbox"/> TESTER
5	C-DI-DI11A-E-01	E	F	06 UPDATE PRINT PER THIS ECO	<input type="checkbox"/> TEST PROG
6	A-PL-7006468-0-0	D	E	06 UPDATE REV PER THIS ECO	<input type="checkbox"/> TOOLING

AFFECTED
 MODEL
 DIAGNOSTICS
 TECH MANUAL
 TESTER
 TEST PROG
 TOOLING
 PLO DMT
 ENG SPEC
 PURCH SPEC

FIELD SERVICE
 AFFECTED
 YES NO
 Customer Change
 Product Line Change

TYPE OF CHANGE
 ELECTRICAL
 MECHANICAL
 MODULE
 ORDER
 PER MODEL
 YES
 NO

DISPOSITION CODES

APPROVAL SIGNATURES

00 - REVISED TO ORDER
 01 - REVISED TO ORDER
 02 - REVISED TO ORDER
 03 - REVISED TO ORDER
 04 - REVISED TO ORDER
 05 - REVISED TO ORDER
 06 - REVISED TO ORDER
 07 - REVISED TO ORDER
 08 - REVISED TO ORDER
 09 - REVISED TO ORDER
 10 - REVISED TO ORDER
 11 - REVISED TO ORDER
 12 - REVISED TO ORDER
 13 - REVISED TO ORDER
 14 - REVISED TO ORDER
 15 - REVISED TO ORDER
 16 - REVISED TO ORDER
 17 - REVISED TO ORDER
 18 - REVISED TO ORDER
 19 - REVISED TO ORDER
 20 - REVISED TO ORDER
 21 - REVISED TO ORDER
 22 - REVISED TO ORDER
 23 - REVISED TO ORDER
 24 - REVISED TO ORDER
 25 - REVISED TO ORDER
 26 - REVISED TO ORDER
 27 - REVISED TO ORDER
 28 - REVISED TO ORDER
 29 - REVISED TO ORDER
 30 - REVISED TO ORDER
 31 - REVISED TO ORDER
 32 - REVISED TO ORDER
 33 - REVISED TO ORDER
 34 - REVISED TO ORDER
 35 - REVISED TO ORDER
 36 - REVISED TO ORDER
 37 - REVISED TO ORDER
 38 - REVISED TO ORDER
 39 - REVISED TO ORDER
 40 - REVISED TO ORDER
 41 - REVISED TO ORDER
 42 - REVISED TO ORDER
 43 - REVISED TO ORDER
 44 - REVISED TO ORDER
 45 - REVISED TO ORDER
 46 - REVISED TO ORDER
 47 - REVISED TO ORDER
 48 - REVISED TO ORDER
 49 - REVISED TO ORDER
 50 - REVISED TO ORDER
 51 - REVISED TO ORDER
 52 - REVISED TO ORDER
 53 - REVISED TO ORDER
 54 - REVISED TO ORDER
 55 - REVISED TO ORDER
 56 - REVISED TO ORDER
 57 - REVISED TO ORDER
 58 - REVISED TO ORDER
 59 - REVISED TO ORDER
 60 - REVISED TO ORDER
 61 - REVISED TO ORDER
 62 - REVISED TO ORDER
 63 - REVISED TO ORDER
 64 - REVISED TO ORDER
 65 - REVISED TO ORDER
 66 - REVISED TO ORDER
 67 - REVISED TO ORDER
 68 - REVISED TO ORDER
 69 - REVISED TO ORDER
 70 - REVISED TO ORDER
 71 - REVISED TO ORDER
 72 - REVISED TO ORDER
 73 - REVISED TO ORDER
 74 - REVISED TO ORDER
 75 - REVISED TO ORDER
 76 - REVISED TO ORDER
 77 - REVISED TO ORDER
 78 - REVISED TO ORDER
 79 - REVISED TO ORDER
 80 - REVISED TO ORDER
 81 - REVISED TO ORDER
 82 - REVISED TO ORDER
 83 - REVISED TO ORDER
 84 - REVISED TO ORDER
 85 - REVISED TO ORDER
 86 - REVISED TO ORDER
 87 - REVISED TO ORDER
 88 - REVISED TO ORDER
 89 - REVISED TO ORDER
 90 - REVISED TO ORDER
 91 - REVISED TO ORDER
 92 - REVISED TO ORDER
 93 - REVISED TO ORDER
 94 - REVISED TO ORDER
 95 - REVISED TO ORDER
 96 - REVISED TO ORDER
 97 - REVISED TO ORDER
 98 - REVISED TO ORDER
 99 - REVISED TO ORDER
 00 - REVISED TO ORDER

Design Engineer John Baker
 Eng No. (OPT) _____
 Field Service (OPT) _____
 Chief Eng. (MODULES ONLY) _____

4:5

FIELD CHANGE ORDER

PCO MM11B - B 0024
PAGE OF

DATA PROCESSING AND DEC-ECO-LOG WILL POST THIS PCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO.

- LEVEL OF URGENCY CODE
- A MANDATORY HIGH PRIORITY
 - B MANDATORY
 - C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
 - D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
 - E PRODUCT IMPROVEMENT - OPTIONAL - LOW PRIORITY

FIELD EFFECTIVITY
Retrofit all MM11-B's

FIELD RETROFIT IS ANTICIPATED IN 100 OF UNITS DEFINED ABOVE

- NO CHARGE TO CUSTOMER - ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE
- STANDARD APPLICABILITY - THIS PCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE, OTHERWISE AT CUSTOMER EXPENSE
- DOCUMENTATION PARTS DEC ON-SITE LABOR
- DEC'S MINIMUM BILLING APPLIES IF THIS PCO IS INSTALLED BY DEC THE DEC LABOR CHARGE ASSURES PCO INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY

CONCRETE PROJECT NUMBER
(FOR FIELD SERVICE REPORTING)

AVAILABILITY DELAY	NO PARTS
PARTS	X

ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

- FIELD OFFICE PCO DISTRIBUTION CODE
- F IMMEDIATE PCO DISTRIBUTION TO ALL DEC FIELD OFFICES
- DF IMMEDIATE PCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TO OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED.

LAST PREVIOUS PCOS D022, C020, C017

RELATED OR PREREQUISITE PCOS

- M729-00003
- MANDATE CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

- PCO KIT DISTRIBUTION
- FMC WILL INITIATE DISTRIBUTION OF PCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE
- ~~FIELD OFFICE WILL INITIATE DISTRIBUTION OF PCO KITS AS DEFINED BELOW~~
KITS AS DEFINED BELOW MAY BE ORDERED AS REQUIRED

CONTENTS OF AN FMC INITIATED KIT					FMC INITIATED PCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES				
PCO	PCO	PARTS	PARTS		D	H	K	W	
CONTENTS OF A FIELD ORDERED KIT									
PCO	PCO	PARTS	PARTS						
	X	X							

PRINT CHANGES ARE MINIMAL AND ARE TO BE MADE MANUALLY IN RED AND GREEN PCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST


VERIFICATION MARKS

INSTALLATION AND TEST PRIORITIES

PARTS REQUIRED


REMARKS
Necessary to improve reliability on existing units.

FIELD SERVICE APPROVAL
Art Zins
5/11, 5/17 (1534) 5/17 800



31057192

<p>ENGINEERING CHANGE ORDER</p>	<p>COORD. MEMORY STAKE TITLE (X-RAIVER)</p>	<p>DES NO D-03-MM-8-03</p>	<p>REV B</p>
	<p>DATE <i>1/1/54</i></p>	<p>DES LOC</p>	<p>GRAPHIC DESCRIPTION</p>



SHEET 2 of 2

ENGINEER NO CHANGE ORDER	CORE MEMORY STACK (Y DRIVER)		Dwg NO D-BS-MM115-03	REV B
	APPN L.H.M.'D	APPN <i>Alvin Smith</i>		

WIRE TABLE - 1943

WIRE TABLE

WIRE NO	WIRE	WIRE	WIRE	TO INH	TO INH	TO INH	TO INH
				GND	GND	GND	GND
				TO INH	TO INH	TO INH	TO INH
				STROBEN	STROBEN	STROBEN	STROBEN

ADD

WIRE ASSY		M.M. 11-8		M.M. 2-20-2011-1-3 E	
BY <i>John R. ...</i>		CHKD <i>...</i>		DATE	
CHKD <i>...</i>		DATE		DRAWING	
DATE		DATE		DRAWING	

FCR

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|--|
| <p>■ G102-B0002 MAR 70
G102-B0003
QUICK SYNOPSIS
8081 IC's replaced by higher speed 74H011 IC's.
QUICK CHECK
74H011 IC's in place of 8081 IC's.
NEW REVISION
Exchange with CS B or later.</p> | <p>■ G103-C0005 JUN 70
QUICK SYNOPSIS
Provides increase to -8.5VDC for sense amplifiers.
QUICK CHECK
Heat sink ADD'd to Q4, C1 and C2 changed from 1000mmfd to 820mmfd.
NEW REVISION
Rework etch D, E to CS D.</p> |
| <p>■ G103-C0002 MAR 70
QUICK SYNOPSIS
Increases system speed.
QUICK CHECK
7410 IC replaced by 74H10 IC.
NEW REVISION
Rework etch B, C to CS B.</p> | <p>■ G225-C0003 JUL 70
QUICK SYNOPSIS
Speeds stabilization of X and Y current generator reference voltage.
QUICK CHECK
R22 changed from 4.7K ohms to 2.2K ohms
NEW REVISION
Rework etch B to CS B.</p> |
| <p>■ G103-C0004 APR 70
QUICK SYNOPSIS
Provides new higher value tripot.
QUICK CHECK
R17 changed from 100 ohm to 500 ohm tripot.
NEW REVISION
Rework etch B, C to CS C.</p> | <p>■ MM11E-C0016 AUG 70
QUICK SYNOPSIS
Provides wire table and wiring instructions to ensure correct memory margins and G102 interchangeability</p> |
| <p>■ G102-B0004 JUN 70
QUICK SYNOPSIS
Decreases turn-off time of the 2007 transistors.
QUICK CHECK
C2, C7, C12, C17 changed from 1000mmfd to 820mmfd.
NEW REVISION
Rework etch D to CS D.</p> | <p>■ MM11E-A0015 SEP 70
QUICK SYNOPSIS
Connects AC LO L and DC LO L signal from the Power Bus to the Unibus to ensure proper Power Fail
QUICK CHECK
BUS AC LO L tied to pin F1
NEW REVISION
Rework to Wire List B.</p> |

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- **M890-C0001 AUG 70**
QUICK SYNOPSIS
Power Fail requires BUS SP1 and BUS SP2
for AC LO and DC LO. (In-plant, new etch B at
CS A.)
QUICK CHECK
R57 and R 4 are 380 ohms.
NEW REVISION
Rework etch B to CS A.
- **M40847B-C0008 OCT 70**
QUICK SYNOPSIS
AC LO and DC LO returns High after assertion
in multiple box systems.
QUICK CHECK
D003 clamping diodes from AC LO (anode)
and from DC LO to +5V line.
NEW REVISION
Rework etch A, B, C to CS D.
- **MM11E-C0017 JAN 71**
MM11E-C0020
QUICK SYNOPSIS
Improves memory performance.
QUICK CHECK
Wire ADD B04F2 to A03E2.
- **M729-C0002 JAN 71**
QUICK SYNOPSIS
Reduces memory cycle time on systems with
8K interleaved memory. (In-plant, new etch C.)
QUICK CHECK
Wire ADD E9 pin 2 to feed-thru near E6 pin 1.
NEW REVISION
Rework etch B to CS B.
- **M1081-C0001 MAR 71**
QUICK SYNOPSIS
Provides 1 unit load on BUS in systems with
16K or more memory.
QUICK CHECK
M1081 replaced M108 module.
NEW REVISION
Rework etch B to CS A.
- **G102-B0008 APR 71**
QUICK SYNOPSIS
Eliminates MM11-F's noise susceptibility
QUICK CHECK
C3, C8, C13, C18 changed from 33mmfd to
120mmfd.
NEW REVISION
Rework etch D to CS D.
- **G225-C0007 MAY 71**
QUICK SYNOPSIS
Prevent heat sinks from shorting to etch
QUICK CHECK
Insulating washers under heat sinks.
- **M7290-C0002 OCT 71**
QUICK SYNOPSIS
Prevents Unibus hang with 88YN asserted
from memory (In-plant, new etch E.)
QUICK CHECK
Wire ADD E8 pin 5 to E7 pin 9
NEW REVISION
Rework etch C to CS D.
- **MM11E-D0022 MAR 77**
QUICK SYNOPSIS
Module protection plate prevents MM11-E
noise interaction with adjacent modules.
QUICK CHECK
Presence of protection plate.
- **MM11E-B0024 MAY 72**
QUICK SYNOPSIS
Reduces noise on TINH and strobe signals.
QUICK CHECK
Wire ADD C01F1 to D0281/C01C2 to
D02T1.
NEW REVISION
Rework to Wire List E.

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

■ **M728-00003 MAY 72
M728-00004**

QUICK SYNOPSIS

Unibus bus with SSYN asserted from
memory.

QUICK CHECK

Wire ADD E3 pin 8 to E3 pin 1.

NEW REVISION

Rework etch B, C to CB C.

■ **M7280-00003 MAY 72**

QUICK SYNOPSIS

Reduced inductance of the TMM H etch cor-
rects noise condition. (In-plant, new etch F.)

QUICK CHECK

Wire ADD E11 pin 8 to feed-thru going to
AR1.

NEW REVISION

Rework etch C, D to CB E.

ECO
QUICK CHECK

DEC/75

MM11-E/F FIELD CODED ECO's

G102	B2, B3, C4, B6
G103	C2, C4, C5, C7
G225	C3, C7
G226	C4
M729	B2, C3 & A & B
M1091	C1
M7290	C2, C3
MM11-E	C15, C16, C17, C20, D22, B24
MM11-F	D1, C3

MM11-E/F ECO PARTS

<u>NAME</u>	<u>ECO#</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G102	#2	1	19-09849	I.C.
	#3	8	13-03064	Resistor
	#4	4	10-00027	Capacitor
		4	13-09995-0	Resistor
		1	16-09996-0	Indicator
	#6	4	10-00018	Capacitor
G103	#2	3	19-09057	I.C.
	#4	1	13-05631	Resistor
	#5	2	13-02602	Resistor
		2	13-09994-0	Resistor
		1	13-00295	Resistor
		2	10-00027	Capacitor
		1	11-09991	Diode
		1	11-09990	Diode
		1	16-09996-0	Conductor
		1	12-10001-0	Heat sink
	#7	1	10-10274	Capacitor
G225	#3	1	13-00417	Resistor
	#7	4	90-08493	Washers
A/R			90-08268	Thermal compound
G226	#4	1	10-10274	Capacitor
N792	#3	1	19-05547	I.C.
M1091	#1	1	M1091 etch "B"	if applicable module
MM11-F	#1	1	74-08490	Memory shield
MM11-E	#2	1	74-08490	Memory shield

MM11-E/F PARTS BREAKDOWN

7006405	- Logic Frame
7006468	- MM11-E Wired assembly
70007263	- MM11-F Wired assembly
G102	- Sense Inhibit Card
G103	- Memory Levels & Gates
G225	- X-Y Current Generator
G226	- X-Y Current Generator
H207	- 4K 16 Bit Core Memory Stack
M109	- Device Select
M729	- MM11-E Control Logic
M1091	- Device Select
M7290	- Control Logic & Timing
MM11-E	- 4K Single Memory Unit
MM11-EK	- 4K Interleaved
MM11-F	- 4K Single Memory Unit
MM11-FF	- Single Parity Memory Unit
MM11-FX	- Interleaved Memory (jumpers)

REVISION DATE APRIL 1976

MM11-E MEMORY		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	
00002	01/70		A		Jumper D01-B1 to E01-E1			NIL					
00003	01/70				Black wire of twisted pair from C02-C2 to E03-C2			NIL					
00006	02/70		B		Jumper A01-S2 to A04-S2			NIL					
C 00015	09/70		C		<u>NOTE:</u> 1) Rework multiple box systems only 2) Must have ECO 5408475-00006 and M930-00001 Jumper A03-S2 to B04-F2			NIL					
C 00016	12/70			1.5	Blue jumper from E01-C1 to E01-E2 looping through logic			NIL					
C 00017	01/71		D		Jumper B04-F1 to A03-E2			NIL					
C 00020	03/71				<u>NOTE:</u> F/S information regarding strobe and threshold level settings			NIL					
D 00022	04/71			1.0	A module protection plate along MM11-E memory bank		1	74-08490					
B 00024	06/72		E	1.0	<u>NOTE:</u> Must have ECO M729 #3 Black wire of twisted pair from E01-C2 to F01-C2.			NIL					

REVISION DATE MAY /76

MM11-E		MEMORY		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED		
00025	05/76				NOTE: Documentation change				NIL						

MM11-F 4K 16 BIT MEMORY				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IFB	PAGE	
															1	OF
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED			
D 00001	3/72			1.0	A module protection plate along each MM11-F bank.			1	74-08490							
00002	5/72				<u>NOTE:</u> Print update of test procedure				Nil							
C 00003	8/72		A	1.0	<u>NOTE:</u> Must have ECO M7290-C0003 Red jumper C01-C2 to E01-T1				Nil							

G102 SENSE INHIBIT CARD				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	3/70		C		<u>NOTE:</u> Documentation change				Nil						
B 00002	3/70	B	D	0.5	E5 is a DEC I.C. 74H01-1 E5 is the 1st I.C. from AS1			1	19-09849						
B 00003	4/70	B	D		<u>NOTE:</u> Supplement to ECO # 2 R4 is a 75 ohm 1/8W resistor R4 is the 1st resistor from AA1			8	13-03064						
C 00004	6/70	C	D	.5	R2 is a 56 ohm 1/4W 5% resistor R2 is the 1st resistor above E2 E2 is a DEC transformer			4 4 1	10-00027 13-09995-0 16-09996-0						
00005	6/71		D		<u>NOTE:</u> See ECO # B6				Nil						
B 00006	4/71	D	D	.25	C3 is a 120 MHP 5% capacitor C3 is the closest capacitor from AA1			4	10-00018						
00007	06/77	E	D		<u>NOTE:</u> 1) PHASE IN DEC 7438 TO REPLACE 74H0.-1 AT E5 2) CHANGES FCO #2 E5 IS A DEC 7438 E5 IS THE LAST I.C. FROM AS1			1 OR 1	19-0949-00 19-11219-01 (SEE ECO #7)						

3103 MEMORY LEVELS & GATES				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAG 1 OF	
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED			
00001	1/70	A	A		<u>NOTE:</u> Print update				N/A							
C 00002	3/70	B	A	.5	E2 is a I.C. DEC 74H10 E2 is the 1st i.c. from AH1			3	19-09057							
00003	3/70		A		<u>NOTE:</u> Print update				Nil							
C 00004	4/70	C	A	.25	R17 is a 500 ohm trim pot R17 is located in bottom left corner			1	13-05631							
C 00005	6/70	D	A	1.0	R1, R2 are 56 ohm, 1/4W, 5% resistors R1 & R2 are the two resistors just right of R4 R4 is the 10W resistor nearest the top right corner			2 2 1 2 1 1 1 1	13-02602 13-09994-0 13-00295 10-00027 11-09991 11-09990 16-09996-0 12-100001-0							
00006	2/71	E	A		<u>NOTE:</u> Print change				Nil							
C 00007	1/72	F	A	.25	C11 is a .22 mfd 50V capacitor C11 is the only capacitor left of the two transistors at AC1			1	10-10274							

REVISION DATE

G225 X - Y CURRENT GENERATOR		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE
													1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED		
C 00003	7/70	B	B	1.0	R22 is a 2.2K 1/4W 5% resistor R22 is the 3rd resistor from bottom left corner	1	13-00417						
00004	7/70	C	C		R5 is a 680 ohm 1/4W 5% resistor R5 is the 1st resistor from A1	4	12-02313 13-00347 13-00394						
00005	8/70	C			<u>NOTE:</u> Print change		Nil						
00006	9/70	D	D		<u>NOTE:</u> New etch rev		Nil						
C 00007	5/71	E	D	1.0	<u>NOTE:</u> Rework only "D" etch boards Insulating washers on all four heat sinks are tight and can not be rotated.	4	90-08493 90-08268 (thermal compound)						

G226 X - Y DECODER SWITCH				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL	DATE INSTALLED	CE	
00001	11/69	A	C		C22 is a .1ufd 50V capacitor C22 is below the two 1/4W resistors on board which are separated by a capacitor				N/A						
00002	3/70	B	C		NOTE: Documentation				Nil						
00003	3/70	C	C		Resistor closest to the bottom left corner is a 120 ohm 1/4W 5% resistor				N/A						
C 00004 6A 6B	11/71	D	D	0.5	C22 is a .22 ufd 50V capacitor C22 is below the two 1/4W resistors on board which are separated by a capacitor			1	10-10274						

M109		DEVICE SELECT		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED		
NONE					NOTE: NO ECO's										

M729 MM11-E Control Logic				ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED		
00001	03/70	A	B		NOTE: 1) New etch rev 2) Rework Etch "A" Revs E5 is aDEC I.C. 74 H 74				N/A						
B 00002	01/71	B	C	1.0	NOTE: 1) Must be installed in interleaved memories and optional for non-interleaved memory 2) Rework etch "B" rev only (ECO #3 has better rework instructions) No capacitor between the 270 OHM and 390 OHM resistors located near the upper left hand corner				NIL						
C 00003 &A &B	06/72 01/73	C	C	1.5	NOTE: ECO# 3 contains ECO #2 & #3 rework instructions for all etch revs Measure an open CKT from E04-09 to E09-01 E09 is the 4th I.C. from AK1			1	19-05547	DZQCQ DZQCA DZQKB					

REVISION DATE

M1091 DEVICE SELECT					ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE
																10
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED		
C 00001	3/71	*	A	N/A	NOTE: MM11-E systems M1091 module if 16K of memory or more				1	M1091 etch "B" (if applicable)						
00002	3/71	A	B		NOTE: MM11-E, MM11-F and MMR11-E memory systems phase in M1091 modules. Check for M1091 module				1	M1091 Etch "B"						

L AND LOGIC		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SLOT	IPB	PAGE	
												1 OF 1	
CS	ETCH #L	ECO H.T.	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
01	2/71	C	D										
02	9/71	D	E D C	2.0									
03	8/72	E	F E D C	4.0									
60004	177	F	F E D C										

Jumper E06-06 to E31-10 feed through
E6 is the 3rd I.C. from AL1
E31 is the last I.C. on board

NOTE: Rework "C" & "D" etch boards
Jumper E03-03 to T07-10 feed through


NOTE: 1) Must have ECO M11-F-C0003
2) Rework all previous etch boards
Jumper E02-08 to AC1

NOTE: DEC 74M01-1 DIRECT SUBSTITUTION
TO DEC 7438
E IS A DEC 7438
E IS

DSMCA thru
DSMCI

NIL

M M M 1 1 - F



digital EQUIPMENT CORPORATION
NATWICK MASSACHUSETTS

Engineering Change
Order Log

MM11-F

4K 16 Bit
22 Mil Memory

800 800

PROCESSOR TYPE PDP-11

MM11F-0001 CODE: DF ML: A
MAR 78 PROBLEM: Under some conditions, when other options are placed along side an MM11-F they fail to operate correctly.
CORRECTION: Install a module protection plate.
In plant effectively. All MM11-F as required.
Field effectively. All MM11-F as required.
Time To Install And Test (8 Hours)
Kit Contents: PCD/Probe And Parts

MM11F-0002 CODE: P ML: B
APR 77 PROBLEM: MM11-F Test Procedure needs updating.
CORRECTION: Update Test Procedure.
IMPLEMENT: MM11-FX print outs are the same as MM11-F.
CORRECTION: Obsolete old MM11-FX Master Drawing but Use New Master Drawing but format as MM11-F to include MM11-FX.
In plant effectively. All documentation change only.

MM11F-0003 CODE: F ML: D WL: A
MAY 72 PROBLEM: Strobe signals and T1M have too much noise on them.
CORRECTION: Install twisted pairs on strobe signals generate another T1M signal and install twisted pairs on three signals.
IMPLEMENT: REAP N signal has too many leads on it.
CORRECTION: Develop another REAP N signal to share the load.
CORRECTION: Solve memory problems caused by DBA transfers that memory disengages don't show up. Also solves slot sensitive GMB, GMB problems.
In plant effectively. Rework immediately.
Field effectively. Retrain all MM11-F.
Time To Install And Test (8 Hours)
Kit Contents: XCU/Probe

F F C O ' S S

ENGINEERING
CHANGE ORDER *0321*

ORIGINATOR Richard Manion *5-2*
TEL EXT 2005 DATE 3/13/72
DESC PROJ NO. 11 07602
COST CENTER NO. 392

ECO NO. *MM11F-0001*
SHEET *1* OF *3*
DATE RECEIVED *3-16-72*
FIRST ISSUE *3-20-72*
FINAL ISSUE

J.S.

PROBLEM
Under some conditions when other options are placed along side an MM11/F they fail to operate correctly.

UNIT TO BE CHANGED

MM11/F
Memory

DESP CODE ***

CORRECTION
Install a module protection plate.

OPTIONS AFFECTED

MM11/F

BREAK-IN/EFFECTIVITY
*Install module protection plate only when problems occur.

PRODUCT LINES AFFECTED

PDP11/20

ITEM NO.	DOCUMENT/PART NO.	OLD REV	NEW REV	DESP CODE	DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED	FIELD SERVICE AFFECTED	TYPE OF CHANGE
1.	A-PL-MM11-F-0	0	A	06	(Memory Assembly MM11/F) Change per this ECO.	<input type="checkbox"/> MODEL	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> ELECTRICAL
2.	7408490	-	-	07	(Module Protection Plate) Add quantity of 1 to drawing index.	<input type="checkbox"/> DIAGNOSTICS	<input type="checkbox"/> Customer Change	<input checked="" type="checkbox"/> MECHANICAL
3.	A-ML-MM11-F	0	A	06	Update per item 1.	<input type="checkbox"/> TECH MANUAL	<input checked="" type="checkbox"/> Product Line Change	<input type="checkbox"/> MODULE
						<input type="checkbox"/> TESTER		ORDER PR MODEL
						<input type="checkbox"/> TEST PROG		<input type="checkbox"/> YES
						<input type="checkbox"/> TOOLING		<input checked="" type="checkbox"/> NO
						<input type="checkbox"/> PKG INST		
						<input type="checkbox"/> ENR SPEC		
						<input type="checkbox"/> PURCH SPEC		

DISPOSITION CODES

- 00 - RETURN TO STOCK
- 01 - (DELETED)
- 02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN)
- 03 - REWORK IMMEDIATELY (REWORK)
- 04 - (DELETED)
- 05 - (DELETED)

APPROVAL SIGNATURES


DESIGN ENGR *Pete Durant*
ENG MGR (OPT) _____
CHECK (OPT) _____

Type-written Hand Signature

ECU MMIF
MMIF REWORK SHEET

SHEET 2 OF 3

1. LOOSEN 2 SCREWS AT POINTS A, CARE SHOULD BE USED AT ALL TIME SO THAT NO WIRES WILL BE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE GND LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINTS B.
3. TIGHTEN SCREWS.





FIELD CHANGE ORDER

PCO MM11P - D10001
PAGE 1 OF 3

DATA PROCESSING AND DEC-SCALES WILL POST THIS PCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO.

FIELD EFFECTIVITY
MM11-P Memory Assembly

- LEVEL OF URGENCY CODE
- A MANDATORY - HIGH PRIORITY
 - B MANDATORY
 - C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
 - D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
 - E PRODUCT IMPROVEMENT - OPTIONAL - LOW PRIORITY

FIELD RETROFIT IS ANTICIPATED IN 5 % OF UNITS DEFINED ABOVE

NO CHARGE TO CUSTOMER - ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE.

STANDARD APPLICABILITY - THIS PCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE, OTHERWISE AT CUSTOMER EXPENSE

DOCUMENTATION 0 PARTS 0 DEC ON-SITE LABOR 0

DEC'S MINIMUM BILLING APPLIES IF THIS PCO IS INSTALLED BY DEC. THE DEC LABOR CHARGE ASSURES PCO INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED, DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY.

DETERMINE PROJECT NUMBER (FOR FIELD SERVICE REPORTING)

AVAILABILITY DELAY	NO PARTS
PARTS <u>None</u>	

ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

FIELD OFFICE PCO DISTRIBUTION CODE

- F IMMEDIATE PCO DISTRIBUTION TO ALL DEC FIELD OFFICES
- DF IMMEDIATE PCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TO OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED.

PCO KIT DISTRIBUTION

- FIC WILL INITIATE DISTRIBUTION OF PCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE
- ~~FIELD INSTALLATION ORDERS (FIOS) WILL BE DISBURSED.~~ KITS, AS DEFINED BELOW, MAY BE ORDERED AS REQUIRED.

CONTENTS OF AN FIC INITIATED BY

Y-O	PCO	PARTS	LABOR

CONTENTS OF A F I O L

FIO	PCO	PARTS	LABOR
	X	X	X

FIC INITIATED PCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES:

D	H	K	W
---	---	---	---

- PRINT CHANGES ARE MINOR AND ARE TO BE MADE MANUALLY IN RED AND GREEN. PCO REVISED PARTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST.

INSTALLATION AND TEST PROCEDURES

- Carefully install module protection plate per PCO instructions. This requires insertion of the plate under existing wire runs which can be easily broken.
- Run maindecs or other programs whose failure indicated the need for this PCO to be implemented. They should now function correctly.

LAST PREVIOUS PCO'S None

RELATED OR PREREQUISITE PCO'S

- MAINDEC CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

VERIFICATION MAINTENANCE

PARTS REQUIRED
Q1 74-08490 Module Protection Plate

NOTE

FIELD SERVICE APPROVAL
Charles Dowey

CDK
3/20 3/24 (3) 3/24 75

CHANGE USE 1/10/72

ORIGINATOR Richard Manion
 TEL EXT 2005 DATE 5/10/72
 DDC PROJ NO 96 06122
 COST CENTER NO. 392

NO. 1 OF 1
 SHEET 1 OF 1
 DATE RECEIVED 5-12-72
 FIRST ISSUE 5-16-72
 FINAL ISSUE 8-4-72

PROBLEM

1. Strobe signals and TIMH have too much noise on them.
2. Read H signal has too many loads on it.
3. Solves memory problems caused by DMA transfers that memory diagnostics don't show up, also, solves slot sensitive G103, G102 problems.

UNIT TO BE CHANGED
 MM11/P
 DDP CODE 03
 OPTIONS AFFECTED

CORRECTION

1. Install twisted pairs on strobe signals, generate another TIMH signal and install twisted pairs on these signals.
2. Develop another Read H signal to share the load.

MM11/P

BREAK-DOWN/EFFECTIVITY
 All MM11/P's shipped after May 31 will have this ECO.
 Rework M7290 module when necessary, all MM11/P's with this ECO have M7290's with ECO #1.

PRODUCT LINES AFFECTED
 PDP11/15
 PDP11/20
 PDP11/45

ITEM NO.	DOCUMENT/PART NO.	REV	REV	DATE	DESCRIPTION OF CHANGE
1	K-WL-MM11-P-07	-	A	06	Update wire list.
2	A-PL-MM11-P-0	A	B	06	Update Rev. per this ECO.
3	A-WL-MM11-P	C	D	06	Update.
4	D-AD-7007263-0-0	-	A	06	Wire Ass'y MM11/P. See final release print.
5	D-BS-MM11-P-03	-	A	06	Core memory stack (2 sheets) See final release print.
6	A-PL-7007263-0-0	-	A	06	Update revision level.

DOCUMENTATION AFFECTED

- MODEL
- DIAGNOSTICS
- TECH MANUAL
- TESTER
- TEST PROG
- TOOLING
- PRO INST
- ENG SPEC
- PURCH SPEC

FIELD SERVICE AFFECTED

YES NO

Customer Change

Product Line Change

TYPE OF CHANGE

- ELECTRICAL
- MECHANICAL
- MODULE

ORDER PR MODEL

YES

NO

DISPOSITION CODES

00 - RETURN TO STOCK

01 - C

02 - L

03 - BLM

04 - (DR)

05 - (C)

06 - (T)

07 - (I)

08 - (S)

09 - (M)

10 - (R)

11 - (A)

12 - (N)

13 - (D)

14 - (U)

15 - (O)

16 - (J)

17 - (K)

18 - (L)

19 - (P)

20 - (H)

21 - (Q)

22 - (R)

23 - (S)

24 - (T)

25 - (V)

26 - (W)

27 - (X)

28 - (Y)

29 - (Z)

30 - (A)

31 - (B)

32 - (C)

33 - (D)

34 - (E)

35 - (F)

36 - (G)

37 - (H)

38 - (I)

39 - (J)

40 - (K)

41 - (L)

42 - (M)

43 - (N)

44 - (O)

45 - (P)

46 - (Q)

47 - (R)

48 - (S)

49 - (T)

50 - (U)

51 - (V)

52 - (W)

53 - (X)

54 - (Y)

55 - (Z)

56 - (A)

57 - (B)

58 - (C)

59 - (D)

60 - (E)

61 - (F)

62 - (G)

63 - (H)

64 - (I)

65 - (J)

66 - (K)

67 - (L)

68 - (M)

69 - (N)

70 - (O)

71 - (P)

72 - (Q)

73 - (R)

74 - (S)

75 - (T)

76 - (U)

77 - (V)

78 - (W)

79 - (X)

80 - (Y)

81 - (Z)

82 - (A)

83 - (B)

84 - (C)

85 - (D)

86 - (E)

87 - (F)

88 - (G)

89 - (H)

90 - (I)

91 - (J)

92 - (K)

93 - (L)

94 - (M)

95 - (N)

96 - (O)

97 - (P)

98 - (Q)

99 - (R)

00 - (S)

APPROVAL SIGNATURES

Typed Name: Pete Durant

Hand Signature: [Signature]

DESIGN ENGR Pete Durant

ENG MGR (OPT) _____

FIELD SERVICE (OPT) _____

CHIEF ENGR (MODULES ONLY) _____

**ENGINEERING CHANGE ORDER
ADD/DELETE SHEET**

ECO NO.
MM11F-00003
Sheet ___ of ___

WIRE LIST NO. K-WL-MM11-F-07

TITLE
MM11/F WIRE LIST
NEW REV. A

MAKE ALL DELETIONS FIRST WHEN INSTALLING

SIGNAL NAME	FROM PIN	TO PIN	COMPONENTS	ADD	DEL
TINH H	C01C1	D02E1			X
TINH H	D03E1	E03E1			X
TINH H	E01E1	F01E1			X
STROBE 00 H	C01R1	D02S1			X
STROBE 01 H	C01R1	E01S1			X
TSS H	F01V2	F01P1			X
TINH L	C01K1	F01S1		X	
TINH L	F01S1	F01U2		X	
TINH L	F01U2	F01V2		X	
TINH 00 H	C01C1	D02E1	WHT	TWP	X
GND	C01C2	D02C2	RED		X
TINH 01 H	F01T2	F01E1	WHT	TWP	X
GND	F01T1	F01C2	RED		X
TINH 01 H	F01T2	E02E1	WHT	TWP	X
GND	F01T1	E02C2	RED		X
STROBE 00 H	C01R1	D02S1	WHT	TWP	X
GND	C01T1	D02T1	RED		X
STROBE 01 H	C01R1	E01S1	WHT	TWP	X
GND	C01C2	E01T1	RED		X

FIELD CHANGE ORDER

FCO MM11F-C 0003
PAGE 1 OF 1

DATA PROCESSING AND SEE-DOO-LOS WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO.

• LEVEL OF URGENCY CODE

- A MANDATORY - HIGH PRIORITY
- B MANDATORY
- C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYSTEMS ARE PRESENT
- D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE, OR SYSTEMS ARE PRESENT
- E PRODUCT IMPROVEMENT - OPTIONAL - LOW PRIORITY

FIELD EFFECTIVITY
Retrofit all MM11-F's

FIELD RETROFIT IS ANTICIPATED IN 100% OF UNITS COVERED ABOVE

NO CHARGE TO CUSTOMER - ALL SEE INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE.

STANDARD APPLICABILITY - THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR MAINTENANCE AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFICIENCY ABOVE, OTHERWISE AT CUSTOMER EXPENSE.

DOCUMENTATION S _____ DATE S _____ SEE CHARGE LABOR S _____
SEE'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY SEE. THE SEE LABOR CHARGE APPLIES FOR INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED, SEE'S LATEST SCHEDULE OF NIGHTLY RATES WILL APPLY.

DISCRETE PROJECT NUMBER
(FOR FIELD SERVICE REPORTING)

AVAILABILITY DELAY	NO PARTS
PAGE	X

ESTIMATED WORK TIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

FIELD OFFICE FCO IDENTIFICATION CODE

F MANDATORY FCO DISTRIBUTION TO ALL SEE FIELD OFFICES
 W MANDATORY FCO DISTRIBUTION TO GENERAL PRODUCT SUPPORT AND TO OFFICE WHERE SUBJECT EQUIPMENT IS LOCATED.

FCO BY DISTRIBUTION

FSC WILL OFFER DISTRIBUTION OF FCO (S) AS DEFERS DELAY IN ACCORDANCE WITH THE DEF DEFERRED FILE.
 ~~DEFERRED DISTRIBUTION~~ DEFERRED DISTRIBUTION OF FCO (S) AS DEFERS DELAY MAY BE ORDERED AS REQUIRED.

LAST PREVIOUS FCO'S DOT

RELATED OR PRECEDENT FCO'S
M7290-00003

- MAJOR CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

CATEGORY OF FCO DEFERS BY

FCO	FCO	FCO	FCO

FCO INSTALLED FOR UNITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE DEF DEFERRED FILE WITH THE FOLLOWING SERVICE STATUS CODES:

CATEGORY OF A FCO DEFERS BY

FCO	FCO	FCO	FCO
	X	X	

D	M	E	W
---	---	---	---

PRINT CHANGES ARE CRITICAL AND ARE TO BE MADE MANUALLY IN RED AND GREEN FCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST.

VERIFICATION METHODS


INSTALLATION AND TEST PROCEDURES

PARTS REQUIRED

NOTE
Necessary to improve reliability on existing units.

FIELD SERVICE APPROVAL
Art Zins

24K
5/16 5/17 (171) 5/18 400



CORE
MEMORY STACK
1111 (X DRIVE)
Lyn Alyn

D-05-MMIF-03



BY A

B-7

GRAPHIC
DESCRIPTION

WIRE TABLE

SIGNAL NAME	FROM PIN	FROM	COLOR	REMARKS	NAME	FROM PIN	TO PIN	COLOR	REMARKS
-10	ADL1	F442	↓ BLU	WIRES MUST BE PLACED RUN TO THE RIGHT OF THE BULK AND PINS					
TINN PIN GND	CP1C1 CP1C2	D22F1 D22C2	WHT BLK	TWP					
TINN PIN GND	F01T2 F01T1	F01F1 F01F2	WHT BLK	TWP	SA1B SA1B L441A	D04Y1 D04Y2 D04Y2	GND GND GND	WHT BLK YEL	3 TWISTED WIRES
					STROBE # GND	CP1A1 CP1A2	D01F1 D01F2	WHT BLK	TWP
		ADD			STROBE # GND	CP1A1 CP1A2	D01F1 D01F2	WHT BLK	TWP
							ADD		

	WIRED ASSY 1984 M11-15	Dwg No. DAD-707263-0-0	REV A
ENGINEER NO CHANGE UNDER	 NAME	LOC.	GRAPHIC DESCRIPTION

FCR

MM11-F
4K 16 BIT 22 MIL MEMOR.1
FCO Cross Reference

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- G102-B0002 MAR 70**
G102-B0003
QUICK SYNOPSIS
8881 IC's replaced by higher speed 74H011 IC's
QUICK CHECK
74H011 IC's in place of 8881 IC's
NEW REVISION
Exchange with CS B or later
- G103-C0002 MAR 70**
QUICK SYNOPSIS
Increases system speed
QUICK CHECK
7410 IC replaced by 74H10
NEW REVISION
Rework etch B C to CS B
- G103-C0004 APR 70**
QUICK SYNOPSIS
Provides new higher value trimpot
QUICK CHECK
R17 changed from 100 ohm to 500 ohm trimpot
NEW REVISION
Rework etch B C to CS C
- G102-B0004 JUN 70**
QUICK SYNOPSIS
Decreases Turn-off time of the 2007 transistors
QUICK CHECK
C2 C7 C12 C17. changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D to CS D
- G103-C0005 JUN 70**
QUICK SYNOPSIS
Provides increase to -6.84VDC for Sense amplifiers
QUICK CHECK
Heat sink ADD'ed to O4 C1 and C2 changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D, E to CS D
- G225-C0003 JUL 70**
QUICK SYNOPSIS
Speeds stabilization of X and Y current generator reference voltage
QUICK CHECK
R22 changed from 4.7K ohm to 2.2K ohms
NEW REVISION
Rework etch B to CS B
- M930-C0001 AUG 70**
QUICK SYNOPSIS
Power Fail requires BUS SP1 and BUS SP2 for AC LO and DC LO (In plant, new etch B at CS A)
QUICK CHECK
R57 and R69 are 390 ohms
NEW REVISION
Exchange with etch B
- 5408475-C0006 OCT 70**
QUICK SYNOPSIS
AC LO and DC LO return high after assertion in multiple box systems
QUICK CHECK
D003 clamping diode from AC LO (anode) and from DC LO to +5V line
NEW REVISION
Rework etch A B C to CS D
- M729-C0002 JAN 71**
QUICK SYNOPSIS
Reduces memory cycle time on systems with 8K interleaved memory (In plant new etch C)
QUICK CHECK
Wire ADD E9 pin 2 to feed-thru near E5 pin 1
NEW REVISION
Rework etch B to CS B

**MM11-F
4K 16 BIT 22 MIL MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

■ M1091-C0001 MAR 71
QUICK SYNOPSIS
Provides 1 unit load on BUS in systems with
16K or more memory
QUICK CHECK
M1091 replaces M109 module
NEW REVISION
Rework etch B to CS A

■ G102-B0006 APR 71
QUICK SYNOPSIS
Eliminates MM11-F's noise susceptibility
QUICK CHECK
C3 C8, C13, C18 changed from 33mmfd to
120mmfd
NEW REVISION
Rework etch D to CS D

■ G225-C0007 MAY 71
QUICK SYNOPSIS
Prevent heat sink from shorting to etch
QUICK CHECK
Insulating washers under heat sinks

■ M7290-C0002 OCT 71
QUICK SYNOPSIS
Prevents Unibus hang with Ssyn asserted
from memory (In-plant, new etch E)
QUICK CHECK
Wire ADD E8 pin 5 to E7 pin 9
NEW REVISION
Rework etch C to CS D

■ MM11F-D0001 MAR 72
QUICK SYNOPSIS
Module protection plate prevents MM11-F
noise interaction with adjacent modules
QUICK CHECK
Presence of protection plate

■ MM11F-C0003 MAY 72
QUICK SYNOPSIS
Reduces noise on TINH and strobe signals
QUICK CHECK
C01C1 to D02E1/C01C2 to D02C2
NEW REVISION
Rework to Wire List A

■ M729-C0003 MAY 72
M729-D0004
QUICK SYNOPSIS
Unibus hang with Ssyn asserted from
memory
QUICK CHECK
Wire ADD E5 pin 6 to E3 pin 1
NEW REVISION
Rework etch B C to CS C

■ M7290-C0003 MAY 72
QUICK SYNOPSIS
Reduced inductance of TINH H etch corrects
noise condition (In-plant, new etch F)
QUICK CHECK
Wire ADD E11 pin 8 to feed-thru going to
AR1
NEW REVISION
Rework etch C, D to CS E

M M M I I L

FCR

MM11-L
8K 16 BIT 16 MIL MEMORY
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

*** Indicates FCO Conjunction Must Be Considered With Prior FCO**

- **G110-B0004 MAY 72**
QUICK SYNOPSIS
Corrects Delay line 3 termination on etch C G110's
QUICK CHECK
R115 changed from 3 K ohms
NEW REVISION
Rework etch C to CS D
COMPATIBILITY
R115 changed from 3K ohms to 1K ohms
- **G110-B0005 MAY 72**
QUICK SYNOPSIS
Corrects C152 insertion polarity (positive terminal) to +5V
QUICK CHECK
Positive terminal of C152 goes to +5V
NEW REVISION
Rework etch C, D to CS E
- **G231-B0001 MAY 72**
QUICK SYNOPSIS
Prevents components on G231 shorting to module above it
QUICK CHECK
Two phenolic 7/16" standoffs on module
NEW REVISION
Rework etch B to CS C
- **G231-D0003 AUG 72**
QUICK SYNOPSIS
Improves -15V and strobe margins when operating at 55°C
QUICK CHECK
Sixteen D672 diodes replace 330 ohm resistors
NEW REVISION
Rework etch B to CS F
- **G231-A0005 AUG 72**
QUICK SYNOPSIS
Improves DC LO and AC LO circuit operation
QUICK CHECK
Wire ADD from R89 to R93
NEW REVISION
Rework etch C to CS E1
- **MM11-S-C0003 OCT 72**
QUICK SYNOPSIS
Module protection plate prevents MM11-S noise interaction with adjacent modules
QUICK CHECK
Presence of module protection plate
- **G110-C0010 NOV 72**
QUICK SYNOPSIS
Data errors occur during the first DATI to any memory bank
QUICK CHECK
Wire ADD E28 pin 13 to E15 pin 10
NEW REVISION
Rework etch C, D, E to CS J
- **G110-D0012 DEC 72**
QUICK SYNOPSIS
Provides print clarification affecting etch C G110's
NEW REVISION
CS E5
- **G110-D0013 DEC 72**
QUICK SYNOPSIS
Ensures PAL and PBL data bits gate high onto the BUS
QUICK CHECK
Wire ADD's E40 pin 4 to pin 13 and E40 pin 9 to pin 12
NEW REVISION
Rework etch C to CS E6
- **G231-D0006 DEC 72**
QUICK SYNOPSIS
G231 prints redrawn to DEC standards
NEW REVISION
CS E4

**MM11-L
8K 16 BIT MIL MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|--|
| <p>■ G108-C0004 DEC 72
QUICK SYNOPSIS
Replaces +3V with INIT L to reset STROBE one-shot
QUICK CHECK
Wire ADD E28 pin 13 to E18 pin 10
NEW REVISION
Rework etch C, E to CS E3</p> | <p>■ G110-B0018 APR 73
QUICK SYNOPSIS
Eliminates noise on STROBE O H etch
QUICK CHECK
Twisted pair E32 pin 8 feed-thru to E58 pin 4 feed-thru/E33 pin 7 to ground side of C4
NEW REVISION
Rework etch C to CS E9</p> |
| <p>■ G110-C0015 MAR 73
QUICK SYNOPSIS
Allows longer memory cycle time on systems with high speed NPR devices
QUICK CHECK
DL3 changed from 100nsec to 125nsec delay
NEW REVISION
Rework etch C to CS E7</p> | <p>□ G108-C0010 JUL 73
QUICK SYNOPSIS
Eliminates noise-induced condition where memory randomly picks up and drops bits
QUICK CHECK
E32 pin 8 feed-thru to E58 pin 14 feed-thru/E33 pin 7 to ground side of C44
NEW REVISION
Rework etch C to CS E7</p> |
| <p>■ G110-CD016
QUICK SYNOPSIS
Eliminates noise on BUS INIT etch
QUICK CHECK
Wire ADD's E4 pin 4 to E7 pin 7, AA1 feed-thru to E7 pin 8
NEW REVISION
Rework etch C to CS E8</p> | <p>□ G110-C0019 NOV 73
QUICK SYNOPSIS
Widening R/W Reset L prevents memory skipping a restore cycle
QUICK CHECK
L-6 pin 8 goes to tap 10 of Delay line
NEW REVISION
Rework etch C to CS E10</p> |
| <p>■ G108-C0008 MAR 73
QUICK SYNOPSIS
Lengthens memory cycle time
QUICK CHECK
DL3 replaced with 125nsec delay
NEW REVISION
Rework etch C to CS E4</p> | <p>■ G108-C0011 NOV 73
QUICK SYNOPSIS
Lengthens R/W flip-flop reset input pulse to prevent skipped memory cycles on a read
QUICK CHECK
E28 pin 8 goes to tap 10 of the Delay line
NEW REVISION
Rework etch C to CS E8</p> |
| <p>■ G108-C0007 MAR 73
QUICK SYNOPSIS
Eliminates noise coupling onto BUS INIT etch from data line etches
QUICK CHECK
Wire ADD E4 pin 4 to E7 pin 7
NEW REVISION
Rework etch C to CS E</p> | |

ECO
QUICK CHECK

NOV./74

MM11-L PARTS BREAKDOWN

G110	- Control and Data Loops
G231	- Memory Driver
H214	- 8K 16 Bit Memory Stack
MM11-L	- One 8K 16 Bit Bank of Memory

JAN./75

MM11-L FIELD CODED ECO'S

G110	B4, B5, C9, C10 & A, D12, D13 & A, C15 & A, C16, B18, C19
G231	B1, D3, A5, D9

March/75

MM11-L ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G110	#4	1	13-00365	Resistor
	#5	1	10-05306	Capacitor
		4	90-08213	Standoffs
	#9	A/R	17-00024	#10 black/wire ground wire
	#10	1	19-05547	I.C.
	#15	1	16-11327	Delay
	#18	1	10-01610	Capacitor
G231	#1	2	90-06892	Standoffs
	#3	16	11-05275	Diode
	#15	A/R	90-09185	Jumper Wire

G110 CONTROL & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE
															1 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00001	03/72	A	C		R118 is a 220 ohm resistor R118 is left of E28 and right of DL3 or possibly under DL3 E28 is the 6th I.C. from BE1 DL3 is the small delay line right of DL1 DL1 is the biggest delay line					N11					
00002	03/72	B	C		DL3 is a 100n sec. delay line with part number D-10100 and/or 1609559 DL3 is a small delay line just right of DL1-08 DL1 is the biggest delay line on board DL3 CHANGED TO 125 N SEC. (P/N-322-1) AND/OR 1611327 BY ECO #15 +15A					N11					
00003	08/72	C	D		R113 is a 120 ohm 1/4W 5% resistor R113 is located at AS1 below DL2 DL2 is between E1 and E2					N11					
B 00004	08/72	D	C	1.0	NOTE: This ECO affects only "C" etch modules R115 is a 1K 1/4W 5% resistor R115 is the 3rd resistor right of DL1-12 DL1 is the biggest delay line				1	13-00365					
B 00005	08/72	E	C	3.0	NOTE: This ECO affects only "C" etch modules C152 is a 6.8 ufd. capacitor with the cathode connected to the + etch on board. C152 is the capacitor right of DL1 -02 DL1 is the biggest delay line				1 4	10-05306 90-08213					

DZMMG
DZMMI

G110 CONTROL & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
															2
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00006	11/72	F	E		R123 is a 390 ohm 1/4W 5% resistor R123 is the closest resistor to BS1				N11						
00007	09/72	E1	C		4 - Standoffs <u>screwed</u> on				N11						
00008	10/72	E2	C		C47 is a .01 uf 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 DO NOT COUNT PULSE TRANSFORMER AS I.C.				N/A						
C 00009	12/72	E3	C	.5	Four #18 gauge black ground jumpers on SIDE ONE INSTEAD OF ON SIDE # TWO				17-00024 (#18 black & white teflon coated)						
C 00010 & 10A	11/72	E4	C	1:0	Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1			1	19-05547	DZQKB					
00011	12/72				<u>NOTE:</u> This ECO deleted				N7A						
D 00012	12/72	E5	C	N/A	<u>NOTE:</u> Print update affecting only "C" etch modules.				N11						

G110 CONTROL. & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
D 00013 & 13A	01/73	E6	C	.5	NOTE: Rework only "C" etch modules Jumper pin 4 to 13 on spare I.C. slot above E40 E40 is the 1st I.C. from CT1					N11	DZQMB				
00014	03/73	K	F		NOTE: This ECO affects only CS "F" etch "E" modules Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1					N/A					
00014A	03/73	K	F		NOTE: This ECO affects E & F etch revs modules DL3 is 125 n sec. delay line with P/N 1-322-1 and or 1611327 DL3 is small delay line right of the big delay line					N/A					
C 00015 & 15A	05/73	E7	C	1.0	NOTE: This ECO affects "C" etch rev modules DL3 is 125 n sec. delay line with P/N L-00-01 and/or 1611327 DL3 is small delay line right of the big delay line				1	16-11327	DZMMG DZQKB DZQGA				
C 00016	06/73	E8	C	2.0	NOTE: Rework only "C" etch rev modules Jumper E04-04 to E07-07					N11	DZMMG DZQKB DZQGA				
00017	12/73	L	F		NOTE: This ECO affect only "E" & "F" etch rev modules Jumper E04-04 to E07-07					N11					

CONTROL & DATA LOOP				ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 4 OF 4
G110															
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME			
B 00018	10/73	E9	C	1.0	NOTE: Rework etch "C" Rev White wire of twisted pair from E32-06 feed through to E58-14 E32 is the 4th I.C from BS1 E58 is the 1st I.C from FC1	1	10-01610								
C 00019	12/73	E10	C	1.0	NOTE: Rework "C" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		NIL	DZQMB							
00020 6A	01/74	M	H		NOTE: Affects "F" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		N/A								
00021	07/74	M E11 E11	H F E C		NOTE: Phase in DEC 8640's to replace DEC 380's		N/A								
00022	09/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18-E22		NIL								

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE		
															1	OF	3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME		
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting				2	90-06892							
00002	8/72	D	D		Four standoffs on module					Nil							
D 00003	8/72	E	D	4.0	NOTE: Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1				16	11-05275	DZMMI						
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E1 is the I.C. closest to the top left corner.					Nil							
A 00005	8/72	E1	C	4.0	NOTE: Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from E1					Nil							
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1					Nil							
00007	9/72	E3	C		NOTE: Print update					Nil							

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors				Nil						
D 00009	12/12	E4	C	N/A	NOTE: Field service clarification for etch "C" modules				Nil						
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor				N/A						
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor				N/A						
00012	4/73	J	E		NOTE: Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1				N/A						
00013	11/73	K	E		NOTE: I.C. substitution cancelled by ECO # 16				N/A						
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.				N/A						
00015	6/74	M	E ALL		NOTE: This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot				N/A						
00016	/74	N E6	E C		NOTE: I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1				N/A						

G231 MEMORY DRIVER			ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE		
														3	OF	3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME				
00017	01/75	P	E		Q6 is a DEC 6534C transistor Q6 is the <u>last</u> transistor from EJ1		N/A									
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire		N/A									

H214 - 8K x 16 BIT MEMORY STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE
00001	6/72	B			NOTE: Print change			Nil					
00002	1/73	C			NOTE: Reference chart for H214, H215, H216 and G645 etch & CS revs			Nil					
00003	6/73	D			NOTE: Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03			N/A					
00004	10/73	E			NOTE: Print correction			Nil					
00005	11/73	F			NOTE: Print correction			Nil					
00006	07/74	H			NOTE: Documentation update			Nil					
00007 SA	12/74	J			NOTE: DOCUMENTATION FOR AMPEX STACK			Nil					

H214 - 8K x 16 BIT MEMORY STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00001	6/72	B			<u>NOTE:</u> Print change			Nil					
00002	1/73	C			<u>NOTE:</u> Reference chart for H214, H215, H216 and G645 etch & CS revs			Nil					
00003	6/73	D			<u>NOTE:</u> Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03			N/A					
00004	10/73	E			<u>NOTE:</u> Print correction			Nil					
00005	11/73	F			<u>NOTE:</u> Print correction			Nil					
00006	/74	H			<u>NOTE:</u> Documentation update								

M M M I I L P

FCR

MM11-LP
8K 16 BIT PARITY (16 BIT) MEMORY MODULE SET
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|---|---|
| <p>■ G231-B0001 MAY 72
QUICK SYNOPSIS
Prevents components on G231 shorting to module above it
QUICK CHECK
Two phenolic 7/16" standoffs on module
NEW REVISION
Rework etch B to CS C</p> | <p>■ G109-C0007 MAR 73
QUICK SYNOPSIS
Eliminates noise coupling onto BUS INIT etch from data line etches
QUICK CHECK
Wire ADD E4 pin 4 to E7 pin 7
NEW REVISION
Rework etch C to CS E</p> |
| <p>■ G231-D0003 AUG 72
QUICK SYNOPSIS
Improves -15V and strobe margins when operating at 55° C
QUICK CHECK
Sixteen D672 diodes replace 330 ohm resistors
NEW REVISION
Rework etch B to CS F</p> | <p>■ C109-C0010 JUL 73
QUICK SYNOPSIS
Eliminates noise induced condition where memory randomly picks up and drops bits
QUICK CHECK
Twisted pair E32 pin 6 feed-thru to E58 pin 14 feed thru/E33 pin 7 to ground side of C44
NEW REVISION
Rework etch C to CS E7</p> |
| <p>■ G231-A0005 AUG 72
QUICK SYNOPSIS
Improves AC LO and DC LO circuit operation
QUICK CHECK
Wire ADD from R89 to R93
NEW REVISION
Rework etch C to CS E1</p> | <p>■ G109-C0011 NOV 73
QUICK SYNOPSIS
Lengthens R/W flip flop reset input pulse to prevent skipped memory cycles on a read
QUICK CHECK
E26 pin 8 goes to top of 10 of the Delay line
NEW REVISION
Rework etch C to CS E8</p> |
| <p>■ G231-D0009 DEC 72
QUICK SYNOPSIS
G231 prints redrawn to DEC standards
NEW REVISION
CS E4</p> | <p>■ G109-C0004 DEC 74
QUICK SYNOPSIS
Replaces +3V with INIT \bar{L} to reset STROBE one shot
QUICK CHECK
Wire ADD E28 pin 13 to E15 pin 10
NEW REVISION
Rework etch C, E to CS E3</p> |
| <p>■ G109-C0008 MAR 73
QUICK SYNOPSIS
Lengthens memory cycle time
QUICK CHECK
DL3 replaced with 125 nsec delay
NEW REVISION
Rework etch C to CS E4</p> | |

ECO
QUICK CHECK

NOV./74

MM11-LP PARTS BREAKDOWN

G109	- Control & Data Loops
G231	- Memory Driver
H215	- 8K 16 Bit Memory Stack
MM11-LP	- One 8K Parity Memory Bank

MAR/76

MM11-LP FIELD CODED ECO'S

G109

- C4, C6, C7, C10, C11

G231

- B1, D3, A5, D9

JAN./75

MM11-LP ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G109	# 3, 3A	8	10-00064	Capacitor
		4	10-01610	Capacitor
		1	13-00309	Capacitor
		5	13-05324	Resistor
G109	# 6	1	16-11327	Delay
G109	# 10	1	10-01610	Capacitor
		A/R	91-07720-09	White Wire
G231	# 1	2	90-06892	Standoffs
G231	# 3	16	11-05275	Diode
G231	# 15	A/R	90-09185	Jumper Wire
M7259	# 4	1	13-01874	Resistor
		1	13-09143-11	Resistor

G109 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIALS	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAM
00001	12/72	F	E		<u>NOTE:</u> New etch Rev			NIL					
00002 6A	12/72	E1	C		Standoffs are screwed on			N/A					
00003 6A	01/73	E2	C		C47 is a .01uf , 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 <u>NOTE:</u> DO NOT COUNT PULSE TRANSFORMER		8 4 1 5	10-000064 10-01610 13-00309 13-05324					
C 00004	01/73	E3	C	2.0	<u>NOTE:</u> Rework G109-YA only for parity memory Jumper from E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1			NIL	DZMFA				
00005	05/73	K	F		<u>NOTE:</u> Affects etch "E" and "F" revs DL3 is 125 n sec. delay line with part number L-00-01 and/or 16-11327 DL3 is the small delay line left of E28 E28 is the 6th I.C. from BE1			NIL					
C 00006	05/73	E4	C	1.0	<u>NOTE:</u> Affects etch "C" revs DL3 is a 125 n sec. delay line part number L-00-01 and/or 16-11327 DL3 is a small delay line left of E28 E28 is the 6th I.C. from BE1		1	16-11327	DZM4G DZQMB				

G109 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL#	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CB NA
C 00007	05/73	E5	C	1.0	NOTE: Affects etch "C" rev G109 & G109-YA modules Jumper E04-04 to E07-07			NIL	VZQB				
00008 6A	06/75	E6	C		NOTE: 1) Affects etch "C" revs. 2) Generate separate G109-YA documentation 3) Change component substitution list R96 is a 82 ohm 1/4W 5% resistor R96 is right of E44 E44 is the 2nd I.C. left of DA1			NIL					
00009	12/73	L	F		NOTE: Affects etch "E" & "F" rev - G109 and G109-YA. Jumper E04-04 to E07-07		1	10-01610					
C 00010	12/73	E7	C	1.0	NOTE: Affects etch "C" rev White jumper from E32-06 to E58-14 E32 is the 4th I.C. from BS1 E58 is the 1st I.C. from FC1		1 A/R	10-01610 91-07720-09					
C 00011	12/73	E8	C	1.0	NOTE: Rework etch "C" rev Jumper or etch run from E26-08 to tap 10 of DL1 E26 is the 4th I.C. from BE1 DL1 is the biggest delay line			NIL	DZQB				
00012 6A	06/74	M	H		NOTE: Affects etch "F" rev Jumper E26-08 to DL1-10 E26 is the 3rd I.C. from BE1 DL1 is the biggest delay line			N/A					

REVISION DATE MAY/76

G109 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SY: UN. I	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAM
00013	07/74	E9	C		NOTE: Phase in DEC 8640 to replace DEC 380 and DEC 7380 chips.		8	19-11469					
00014	05/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18 to E22.			NIL					

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE	
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting			2	90-06892						
00002	8/72	D	D		Four standoffs on module				Nil						
D 00003	8/72	E	D	4.0	NOTE: Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1			16	11-05275	DZMMI					
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E2 is the I.C. closest to the top left corner.				Nil						
A 00005	8/72	E1	C	4.0	NOTE: Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from E1				Nil						
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1				Nil						
00007	9/72	E3	C		NOTE: Print update				Nil						

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors					N11					
D 00009	12/12	E4	C	N/A	<u>NOTE:</u> Field service clarification for etch "C" modules					N11					
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor					N/A					
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor					N/A					
00012	4/73	J	E		<u>NOTE:</u> Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1					N/A					
00013	11/73	K	E		<u>NOTE:</u> I.C. substitution cancelled by ECO # 16					N/A					
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.					N/A					
00015	6/74	M	E ALL		<u>NOTE:</u> This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot					N/A					
00016	/74	N E6	E C		<u>NOTE:</u> I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1					N/A					


G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00017	01/75	P	E		Q6 is a DEC 6534C transistor Q6 is the <u>last</u> transistor from EJ1				N/A						
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire				N/A						

H215 8K x 18 BIT MEMORY STACK				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH #	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE	
00001	7/73	A			<u>NOTE:</u> Print change				NIL						
00002 8A	12/74				<u>NOTE:</u> DOCUMENTATION FOR AMPEX STACK				NIL						

M M M I I S

MM11-S PARTS BREAKDOWN

7008816	-Backplane Assembly
7008855-2B	-11/45 MM11 Power Cable (old)
7008909	-11/40 MM11 Power Cable (old)
7009562	-G772 System Unit Harness (new)
G110	-Control & Data Loops
G231	-Memory Drivers
H214	-8K Bank of Core Memory
BC11-A	-Unibus Cable
M920	-Unibus Jumper
MM11-S	-Single Backplane Unit





MM11-S
8K 16 Bit,
890 ns Memory

2358 R824
PROCESSOR TYPE PDP-11/45

MM11S-0001 CODE D WL A
APR 72 PROBLEM Missing wires on MM11S back plane for signal
SP11
CORRECTION Add three wires to Wire List
In plant effectively 48 rework immediately

MM11S-0002 CODE P
SEP 72 CORRECTION Make corrections to Drawing Directory BDD
MM11 S
In plant effectively 48 documentation change only

MM11S-0003 CODE P
JUN 72 PROBLEM Under some conditions when other options are
plugged inside an MM11S they fail to operate correctly
CORRECTION Install a 0740000 module protection plate

NOTE This P.C. is required when other options such as KW11P etc are
physically mounted next to an MM11S memory. Noise generated by the
MM11S may interact with adjacent modules
In plant effectively 48 phase in
Field effectively Retrait all MM11S memories as required
(M) revision B is created Time To Install And Test 5 Hour
Kit Contents PCU Prints And Parts

MM11S-0004 CODE P DD C
NOV 72 CORRECTION Add Manufacturing Test Procedures for MM11
K 1 M and S and drawing ANPMM11S Modules and systems to
Drawing Directory
In plant effectively 48 documentation change only

F E C O S

ORDER

ORIGINATOR R. Manion 1-3
 TEL EXT 2005 DATE 10/16/72
 DESK PROJ NO. 876A 063M
 COST CENTER NO. 392
 W-0-1733

ECO NO. MMMS-00002
 SHEET 1 OF 2
 DATE RECEIVED 10-17-72
 FIRST ISSUE 10-19-72
 FINAL ISSUE 11-14-72

PROBLEM

Under some conditions when other options are placed along side an MM1/S they fail to operate correctly.

UNIT TO BE CHANGED

MM1/S
 MEMORY

EMP CODE *02

OPTIONS AFFECTED

MM1/S
 MM1/SP

CORRECTION

Install a module protection plate.

BREAK-IN/EFFECTIVITY

*Install on all units in production.

Install in field if required.

PRODUCT LINES AFFECTED

PDP11/45

ITEM NO.	DOCUMENT/PART NO.	OL. REV. VALUE			DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED	FIELD SERVICE AFFECTED	TYPE OF CHANGE
		REV	REV	VALUE				
1.	B-DD-MM1-S	A	B	06	(Drawing Directory) Change per this ECO. (Module Protection Plate) Add B-MD-7408490-0 to drawing directory.	<input type="checkbox"/> MODEL <input type="checkbox"/> DIAGNOSTICS <input type="checkbox"/> TECH MANUAL <input type="checkbox"/> TESTER <input type="checkbox"/> TEST PROG <input type="checkbox"/> TOOLING <input type="checkbox"/> PFG INST <input type="checkbox"/> ENG SPEC <input type="checkbox"/> PURCH SPEC	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Customer Change <input checked="" type="checkbox"/> Product Line Change	<input type="checkbox"/> ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE ORDER PR MODEL <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

DISPOSITION CODES

- 00 - RETURN TO STOCK
- 01 - (DELETED)
- 02 - USE PART IN STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN)
- 03 - BEFORE IMMEDIATELY (REWORK)
- 04 - (DELETED)
- 05 - (DELETED)
- 06 - (DELETED)
- 07 - (DELETED)
- 08 - (DELETED)
- 09 - (DELETED)
- 10 - (DELETED)

APPROVAL SIGNATURES

DESIGN ENGR Rita Durant
 ENG MOR (OPT) _____
 FIELD SERVICE (OPT) _____
 CHIEF ENGR (MODULES ONLY) _____

FIELD CHANGE ORDER

FCO MM11S - C 0003

PAGE OF

DATA PROCESSING AND DEC ECO LOG WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO

FIELD ACTIVITY
Retrofit all MM11-S memories as required

*** LEVEL OF URGENCY CODE**

- A MANDATORY HIGH PRIORITY
- B MANDATORY
- C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
- D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
- E PRODUCT IMPROVEMENT OPTIONAL LOW PRIORITY

FIELD RETROFIT IS ANTICIPATED IN % OF UNITS DEFINED ABOVE

USE REF. PRODUCT NUMBER
FOR FIELD SERVICE REPORTING: **W67**

NO CHARGE TO CUSTOMER ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE

STANDARD APPLICABILITY THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE, OTHERWISE AT CUSTOMER EXPENSE

AVAILABILITY DELAY NO PARTS

PARTS **None**

DOCUMENTATION PARTS DEC ON-SITE LABOR

DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC. THE DEC LABOR CHARGE ASSUMES FCO INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED, DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY.

ESTIMATED DOWN TIME FOR
INSTALLATION AND TESTING **0.5** HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

FIELD OFFICE FCO DISTRIBUTION CODE

- F** IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES
- DF** IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT

LAST PREVIOUS FCO'S **None**

RELATED OR PREREQUISITE FCO'S

FCO KIT DISTRIBUTION

KITS, AS DEFINED BELOW, MAY BE ORDERED AS REQUIRED

- MAINTENANCE CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

CONTENTS OF AN FSC INITIATED KIT

FCO	FCO	PRINTS	PARTS

FSC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EOP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES

CONTENTS OF A FIELD ORN. KIT

FCO	FCO	PRINTS	PARTS
	X	X	X

D	H	A	B		
---	---	---	---	--	--

VERIFICATION MANDECS

11-DZQMB

INSTALLATION AND TEST PRIORITIES

PARTS REQUIRED

Q1 74-08490 Module
protection plate

NOTE This FCO is required when other options such as KW11-P, etc. are physically mounted next to an MM11-S memory. Noise generated by the MM11-S may interact with adjacent modules.

FIELD SERVICE APPROVAL


Art Zins

ACK

10/30 450

MM115 REWORK SHEET

1. LOOSEN 2 SCREWS AT POINTS A. CARE SHOULD BE USED AT ALL TIME SO THAT NO WIRES ARE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE GND LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINT B.
3. TIGHTEN SCREWS.



MM115-00003
Sheet 2 of 2

FCR

MM11 B
8K, 16 BIT 18 MIL MEMORY
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- **Q231-B0001 MAY 71**
QUICK SYNOPSIS
Prevents components on Q231 shorting to module above it.
QUICK CHECK
Two phenolic 7/16" standoffs on module.
NEW REVISION
Rework etch B to CS C.
- **Q110-B0004 MAY 72**
QUICK SYNOPSIS
Corrects delay line 3 termination on C etch G110's.
QUICK CHECK
R115 changed from 3K to 1K ohm.
NEW REVISION
Rework etch C to CS D.
- **Q110-B0005 MAY 72**
QUICK SYNOPSIS
Corrects C152 insertion polarity (positive terminal) to +5V.
QUICK CHECK
Positive terminal of C152 goes to +5V.
NEW REVISION
Rework etch C, D to CS E.
- **Q231-D0003 AUG 72**
QUICK SYNOPSIS
Improves -15V and strobe margins when operating at 55°C.
QUICK CHECK
Sixteen D672 diodes replace 330 ohm resistors.
NEW REVISION
Rework etch B to CS F.
- **Q231-A0006 AUG 72**
QUICK SYNOPSIS
Improves AC LO and DC LO circuit operation.
QUICK CHECK
Wire ADD from R89 to R93.
NEW REVISION
Rework etch C to CS E1.
- **Q110-D0012 DEC 72**
QUICK SYNOPSIS
Provides print clarification affecting etch C G110's.
NEW REVISION
CS E5.
- **Q110-D0013 DEC 72**
QUICK SYNOPSIS
Ensures PAL and PBL data bits gate high onto the Bus.
QUICK CHECK
Wire ADD's E40 pin 4 to pin 13 and E40 pin 9 to pin 12.
NEW REVISION
Rework etch C to CS E6.
- **Q110-C0015 MAR 73**
QUICK SYNOPSIS
Allows longer memory cycle time on systems with high speed NPR devices.
QUICK CHECK
DL3 changed from 100nsec to 125nsec delay.
NEW REVISION
Rework etch C to CS E7.
- **Q110-C0016 MAR 73**
QUICK SYNOPSIS
Eliminates noise on BUS INIT etch.
QUICK CHECK
Wire ADD S E4 pin 4 to E7 pin 7, AA1 feed-thru to E7 pin 6.
NEW REVISION
Rework etch C to CS E8.

**MM11-B
8K, 18 BIT 18 MIL MEMORY
PCO Cross Reference**

**A Chronological Listing of Field Retrofit PCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates PCO Conjunction Must Be Considered With Prior PCO

■ G110-B0018 APR 73

QUICK SYNOPSIS

Eliminates noise on STROBE O H csh.

QUICK CHECK

E32 pin 8 lead- thru to E33 pin 4 lead-
thru/E33 pin 7 to ground side of C44.

NEW REVISION

Rework csh C to CS 8B.

■ G110-C0019 NOV 73

QUICK SYNOPSIS

Lengthening R/W RESET L prevents memory
skipping a Restore cycle.

QUICK CHECK

E28 pin 8 goes to Tap 10 of Delay line.

NEW REVISION

Rework csh C to CS E10.

■ MM11B-C0008 OCT 73

QUICK SYNOPSIS

Module protection plate eliminates MM11-B
noise interaction with adjacent modules.

QUICK CHECK

Presence of protection plate.



NOV/74

MM11-S PARTS BREAKDOWN

7008816	-Backplane Assembly
7008855-2B	-11/45 MM11 Power Cable (old)
7008909	-11/40 MM11 Power Cable (old)
7009562	-G772 System Unit Harness (new)
G110	-Control & Data Loops
G231	-Memory Drivers
H214	-8K Bank of Core Memory
BC11-A	-Unibus Cable
M920	-Unibus Jumper
MM11-S	-Single Backplane Unit

JAN/75

MM11-S ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G110	# 4	1	13-00365	Resistor
	# 5	1	10-05306	Capacitor
		4	90-08213	Standoffs
	# 9	A/R	17-00024	# 10 black/white gd.wire
	#10	1	19-05547	I.C.
	#15	1	16-11327	Delay
	#18	1	10-01610	Capacitor
G231	# 1	2	90-06892	Standoffs
	# 3	16	11-05275	Diode
	#15	A/R	90-09185	Jumper wire
MM11-S	# 3	1	74-08490	Shield

JAN./75

MM11-S FIELD CODED ECO'S

G110	B4, B5, C9, C10 & A, D12, D13 & A, C15 & A, C16, B18, C19
G231	B1, D3, A5, D9
MM11-S	C3

MM11-S 8K 16 BIT MEMORY				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	4/72		A		Jumper A01-U1 to A02-U1				Nil						
00002	9/72				<u>NOTE:</u> Print change				Nil						
C 00003	10/72			.5	A module protection plate beside MM11-S memory bank.			1	74-08490						
00004	11/72				<u>NOTE:</u> Adds test procedures for MM11-K, L, M, S and SP modules and systems				Nil						
00005	10/73				Jumper C02-A2 to F01-A2				Nil						
00006	2/74				<u>NOTE:</u> New harness (7009562) introduced for 15 pin power distribution. 11/40 and 11/45 with serial numbers greater than 6000 and 2000 respectively have a G772 system unit harness				N/A						
00007	05/75				<u>NOTE:</u> Document update				NIL						
00008	05/76				<u>NOTE:</u> Documentation update				NIL						

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
													1 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CC NAME	
00001	03/72	A	C		R118 is a 220 ohm resistor R118 is left of E28 and right of DL3 or possibly under DL3 E28 is the 6th I.C. from BE1 DL3 is the small delay line right of DL1 DL1 is the biggest delay line		N11						
00002	03/72	B	C		DL3 is a 100n sec. delay line with part number D-10100 and/or 1609559 DL3 is a small delay line just right of DL1-08 DL1 is the biggest delay line on board DL3 CHANGED TO 125 N SEC. (P/N-322-1) AND/OR 1611327 BY ECO #15 +15A		N11						
00003	08/72	C	D		R113 is a 120 ohm 1/2W 5% resistor R113 is located at AS1 below DL2 DL2 is between E1 and E2		N11						
B 00004	08/72	D	C	1.0	NOTE: This ECO affects only "C" etch modules R115 is a 1K 1/2W 5% resistor R115 is the 3rd resistor right of DL1-12 DL1 is the biggest delay line	1	13-00365					DZMMG DZMMI	
B 00005	08/72	E	C	3.0	NOTE: This ECO affects only "C" etch modules C152 is a 6.8 ufd. capacitor with the cathode connected to the + etch on board. C152 is the capacitor right of DL1 -02 DL1 is the biggest delay line	1 4	10-05306 90-08213						

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00006	11/72	F	E		R123 is a <u>390</u> ohm $\frac{1}{4}$ W 5% resistor R123 is the closest resistor to BS1			N11					
00007	09/72	E1	C		4 - Standoffs <u>screwed</u> on			N11					
00008	10/72	E2	C		C47 is a <u>.01</u> uf 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 DO NOT COUNT PULSE TRANSFORMER AS I.C.			N/A					
C 00009	12/72	E3	C	.5	Four #18 gauge black ground jumpers on SIDE ONE INSTEAD OF ON SIDE # TWO			17-00024 (#18 black & white teflon coated)					
C 00010 & 10A	11/72	E4	C	1.0	Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1		1	19-05547	DZQKB				
00011	12/72				<u>NOTE:</u> This ECO deleted			N7A					
D 00012	12/72	E5	C	N/A	<u>NOTE:</u> Print update affecting only "C" etch modules.			N11					

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
D 00013 & 13A	01/73	E6	C	.5	NOTE: Rework only "C" etch modules Jumper pin 4 to 13 on spare I.C. slot above E40 E40 is the 1st I.C. from CT1			N11	DZQMB				
00014	03/73	K	F		NOTE: This ECO affects only CS "F" etch "E" modules Jumper E15-10 to E28-13 E15 is the 4th I.C, from AV1 E28 is the 6th I.C. from BE1			N/A					
00014A	03/73	K	F		NOTE: This ECO affects E & F etch revs modules DL3 is 125 n sec. delay line with P/N 1-322-1 and or 1611327 DL3 is small delay line right of the big delay line			N/A					
C 00015 & 15A	05/73	E7	C	1.0	NOTE: This ECO affects "C" etch rev modules DL3 is 125 n sec. delay line with P/N L-00-01 and/or 1611327 DL3 is small delay line right of the big delay line		1	16-11327	DZMMG DZQKB DZQGA				
C 00016	06/73	E8	C	2.0	NOTE: Rework only "C" etch rev modules Jumper E04-04 to E07-07			N11	DZMMG DZQKB DZQGA				
00017	12/73	L	F		NOTE: This ECO affect only "E" & "F" etch rev modules Jumper E04-04 to E01-07			N11					

CONTROL & DATA LOOP				ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 4 OF 4
G110															
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME			
B 00018	10/73	E9	C	1.0	NOTE: Rework etch "C" Rev White wire of twisted pair from E32-06 feed through to E58-14 E32 is the 4th I.C from BS1 E58 is the 1st I.C from FC1	1	10-01610								
C 00019	12/73	E10	C	1.0	NOTE: Rework "C" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		NIL	DZQMB							
00020 6A	01/74	M	H		NOTE: Affects "F" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		N/A								
00021	07/74	M E11 E11	H F E C		NOTE: Phase in DEC 8640's to replace DEC 380's		N/A								
00022	09/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18-E22		NIL								

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE		
															1	OF	3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME					
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting	2	90-06892										
00002	8/72	D	D		Four standoffs on module		Nil										
D 00003	8/72	E	D	4.0	<u>NOTE:</u> Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1	16	11-05275	DZMMI									
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E2 is the I.C. closest to the top left corner.		Nil										
A 00005	8/72	E1	C	4.0	<u>NOTE:</u> Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from EL1		Nil										
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1		Nil										
00007	9/72	E3	C		<u>NOTE:</u> Print update		Nil										

3231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors					Nil					
00009	12/12	E4	C	N/A	NOTE: Field service clarification for etch "C" modules					Nil					
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor					N/A					
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor					N/A					
00012	4/73	J	E		NOTE: Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1					N/A					
00013	11/73	K	E		NOTE: I.C. substitution cancelled by ECO # 16					N/A					
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.					N/A					
00015	6/74	M	E ALL		NOTE: This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot					N/A					
00016	/74	N E6	E C		NOTE: I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1					N/A					

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00017	01/75	P	E		Q6 is a DEC 6534C transistor Q6 is the <u>last</u> transistor from EJ1				N/A						
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire				N/A						

H214 - 8K x 16 BIT MEMORY STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH NIL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL DATE	DATE INSTALLED	CD
00001	6/72	B			<u>NOTE:</u> Print change			NIL					
00002	1/73	C			<u>NOTE:</u> Reference chart for H214, H215, H216 and G645 etch & CS revs			NIL					
00003	6/73	D			<u>NOTE:</u> Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03			N/A					
00004	10/73	E			<u>NOTE:</u> Print correction			NIL					
00005	11/73	F			<u>NOTE:</u> Print correction			NIL					
00006	07/74	H			<u>NOTE:</u> Documentation update			NIL					
00007 SA	12/74	J			<u>NOTE:</u> DOCUMENTATION FOR AMPEX STACK			NIL					

MINIMUM

FCR

**MM11-U
16K CORE MEMORY/PARITY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

Q235-80000 SEP 78

QUICK SYNOPSIS

Marginal memory under conditions of high
drive current

QUICK CHECK

750 ohm resistor at + symbol near large etch

NEW REVISION

Rework etch D to CS N

ECO
QUICK CHECK

APRIL/77

NOTE: 1) MM11-U/UP are combined together for convenience

MM11-U/UP PARTS BREAKDOWN

G114	- 16K sense memory
G235	- 16K X-Y driver
H217-C	- parity memory stack (16K X 18 bit)
H217-D	- memory stack (16K X 16 bit)
M8239	- 16K timing module
MM11-U/UP	- 16K Core Memory/Parity

MM11-U/UP FIELD CODED ECO's

G114	- 15
G235	- 59

MM11-U/UP ECO PARTS

<u>NAME</u>	<u>ECO#</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G235	49	1	13-05281-00	RESISTOR

G114 16K SENSE INHIBIT		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00001	10/73	B	B		<u>NOTE:</u> Cancelled By ECO# 1A		.	NIL					
00001A	10/73	B	B		Gnd Jumper from FT1 and along the bottom of the board		A/R	91-07470-00					
00002	11/73	C	B		R108 is a <u>56 OHM</u> , 1/2W, 5% resistor R108 to the right of T103 T103 is a transformer along AC1 near handle side.		.	N/A					
00003	10/74	D	C		<u>NOTE:</u> New Etch Rev.			NIL					
00004	04/75	E	C		<u>NOTE:</u> Part substitution due to shortage			N/A					
I 00005	05/75	F	C	.5	<u>NOTE:</u> Affects only etch "C" rev's Measure open circuit from the top left metal handle to ground			NIL					

G235		16K X-Y DRIVER		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 2
					MF11-U										
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	07/73	D	D		R35 is a 3.16K, 1/8W, 1% resistor R35 is located below W4 W4 is left of E2-01 E2 is the 2nd I.C. from AT1			1 1	13-00229 13-03045						
00002	09/73	E	D		R92 is NOT a 330ohm, 1/4W, 5% resistor R92 is the 4th component above R101 R101 is 220 ohm, 2W resistor left at AT1			1 2 1	11-03441 13-00271 13-02379						
00003	11/73	F	D		R29 is a 120K, 1/4W 5% resistor R29 is the 1st resistor above Q14 Q14 is the transistor above E4 E4 is the 2nd I.C. from BL1				N/A						
00004	01/74	H	D		D2, D3, D4 are deleted No diodes between E2 and R18 R18 is a 100ohm resistor, above E2			1 1	15-05321 19-10466						
00005	04/74	J	D		C47 is a .022 ufd capacitor C47 is the 1st capacitor below T2 T2 is a transformer at the far left of AM1			2 1	10-11683 13-04855						
00006	08/74	K	D		Delete C44 Only one 47ufd, 20V, 10% capacitor still present (not two) between Q12 and Q13 Q12 and Q13 are the 1st and 2nd transistors from AE1				NIL						

G235 16K X-Y DRIVER		ETCH	OPTION	OPTION SERIALS	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB
			MF11-U/UP MM11-U/UP									
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00007	04/75	L	D		<u>NOTE</u> : Parts substitution due to shortages		NIL					
I 00008	06/75	L	D		<u>NOTE</u> : Must have if used on MA20-M for PDP10 R23 is an 1K 1/2W resistor R23 is the only resistor left of AA1	1 1	13-00364 13-02388					
I 00009 6A	06/76	N	D		R103 is a 75 ohm 1W 5% resistor R103 is immediately right of Q12 Q12 is the 2nd transistor from AC1							

H217 16K STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAD	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1	
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	05/74				<u>NOTE: Manufacturing Change</u>			NIL						
00002	07/74				<u>NOTE: Document Change</u>			NIL						
00003	10/74	B	E		<u>NOTE: Rework H217-B and C (18 or 19 Bit)</u> Diodes D29, D30 are deleted D29, D30 were Diodes left of CE1 but right of the resistor network			NIL						
00004	03/76	C	E		<u>NOTE: Manufacturing change.</u>			NIL						

REVISION DATE MAY/76

M8293		16K UNIBUS TIMING		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL#	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	10/73	B	B		NOTE: This is a mandatory ECO Measure continuity from E21-03 to E25-13 E21 is the 2nd I.C. from CL1 E25 is below E21				NIL						
00002	11/73	C	B		NOTE: This is a mandatory ECO Measure continuity from E03-05 to DL3-05 DL3 is the only delay line left of AR1				NIL						
00003 6A	06/74	U	C		NOTE: New etch rev				N/A						
00004	06/75	E	C		NOTE: Phase in DEC 8640 to replace DEC 380				N/A						
00005	06/76	F	C B		NOTE: Introduces M8293-YB for XM15 M8293-YB can be distinguished by checking for jumper from E38-12 to E38-13 E38 is the 4th I.C. from DT1				NIL						