



File Download: workstation

Contents of /ftp/swhelp/xact_ws

Files/Patches/Information for the XACT core tools on workstation platf

=====		
Filename	Size	File Description
=====		
4kefixhp.tar	1296KB	Fixes for 4KE Pre-release v1.00 (HP Platform)
4kefixsn.tar	1340KB	Fixes for 4KE Pre-release v1.00 (Su Platform)
cdicsh.tar	12KB	C-shell script for non-graphical install XACT 5.2.0 or 5.2.1 for SunOS, HPUX, S and RS6000 Operating Systems)
chkinihp.tar	228KB	HP version - program to check the INIT=
chkinirs.tar	295KB	RS6000 version - program to check the INIT=
chkinisn.tar	271KB	Sun version - program to check the INIT=
gui52tar.z	6672KB	5.2.0 RS6000 executables that bring up a GUI. Includes XDE, XACT, MAKEPROM, and XDELAY. This is a fix for problems running 5.2.1 GUIs on a RS6000 PowerPC platform using AIX 4.x.x For IBM RS6000
lcaxnfhp.tar	294 kB	Patch for lca2xnf 521. Fixes bug where INIT= string values for RAMS are swapp Also, includes fixes in which LCA2XNF writes out 5-input gates for XC5200 designs. Solution #: 1454 For HP-UX Uploaded: 03-28-97
lcaxnfsn.tar	345 kB	Patch for lca2xnf 521. Fixes bug where INIT= string values for RAMS are swapp Also, includes fixes in which LCA2XNF writes out 5-input gates for XC5200 designs. Solution #: 1454 For Solaris 2.x, SunOS 4.x Uploaded: 03-28-97
solarisl.tar	301KB	XACT license Manager for Solaris. Read the

```

                                readme.txt for installation instructio
x520fxhp.tar      418KB  Fixes for XACT 5.2 (HPPA platform)
x520fxsn.tar      463KB  Fixes for XACT 5.2 (Sun platform)
xchkr_hp.tar      307KB  Version of XChecker to fix Readback
                        for 4KE devices.
                        For SunOS4.x and Solaris
xchkr_sn.tar      294KB  Version of XChecker to fix Readback
                        for 4KE devices.
                        For SunOS4.x and Solaris
```